

Recall Detail

Ref No	10000172
Manufacturer	Toyota
Vehicle Class	Light Bus
Model/Type	Coaster
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	LPG tank replacement
Progress	Completed
Affected Vehicle Identification Number (VIN)	Not applicable
Description of Defect, how it came to light, and possible consequences if ignored.	The LPG tank of Hong Kong Coaster has a mechanism to automatically stop the filling LPG at the 85% of tank capacity. However, on some Coasters, LPG is kept filling even the tank capacity exceeds 85%.
Remedial Action	Replace the LPG tank
Build Dates	November 2004 ~ March 2005
Launch Date	August 2005
Date of Recall Completion	6 December 2011