

## Recall Detail

<b>Ref No</b>	<b>10000173</b>
<b>Manufacturer</b>	Toyota
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Previa
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4988)
<b>Subject</b>	Ignition coil replacement
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The secondary ignition coil may be broken by the engine heat affection and the ignition coil output will be reduced and cause rough idling. The exhaust catalytic converter will be damaged if the vehicle is being operated under this condition.
<b>Remedial Action</b>	Ignition coil and catalytic converter will be inspected and replaced if necessary.
<b>Build Dates</b>	December 1999 ~ December 2000
<b>Launch Date</b>	October 2005
<b>Tentative Date of Recall Completion</b>	July 2017 (completed)