

Recall Detail

Ref No	10000260
Manufacturer	Toyota
Vehicle Class	Private Car
Model/Type	Crown Royal
Dealer (phone no)	Crown Motors Limited (Tel: 2880 4988)
Subject	Rear brake caliper inspection
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The slide pin of the rear brake caliper may rust & cause improper movement of the caliper resulting in uneven brake pads wear.
Remedial Action	Check & grease up the rear brake caliper sliding pin or change the rear brake caliper if necessary.
Build Dates	January 2005 ~ November 2006
Launch Date	July 2008
Tentative Date of Recall Completion	July 2017 (completed)