

## Recall Detail

|   |   |
|---|---|
| <b>Ref No</b>   | <b>10000351</b>   |
| <b>Manufacturer</b>   | Daimler AG  |
| <b>Vehicle Class</b>  | Van/Private car   |
| <b>Model/Type</b>   | Vito/Viano  |
| <b>Dealer (phone no)</b>  | Aberdeen Service Centre: 2552 8298<br>Quarry Bay Service Centre: 2563 4333<br>Hunghom Service Centre: 2363 9396<br>Kwai Chung Service Centre: 2427 3355<br>Yuen Long Service Centre: 2473 3171<br>Macau Service Centre: 2885 0138<br>Zung Fu Commercial Vehicle Service Centre: 2637 2988   |
| <b>Subject</b>  | Replace additional fan relay (8394089)  |
| <b>Progress</b>   | <b>Completed</b>  |
| <b>Affected Vehicle Identification Number (VIN)</b>                                       | List as below:  |
| <b>Description of Defect, how it came to light, and possible consequences if ignored.</b> | It is possible that the air conditioning fan relay overheats in various operating conditions (e.g. high outside temperature, high engine temperature, continuous operation of air conditioning). This leads to the possibility that conductor tracks, solderings and components inside of the relay are overloaded and as a result a short circuit and fusing or fire damage may occur. |
| <b>Remedial Action</b>  | Exchange the air conditioning fan relay on the affected vehicles as a precautionary measure as part of a recall.  |
| <b>Build Dates</b>  | 23/04/2008 - 21/10/2010   |
| <b>Launch Date</b>  | 21/3/2011   |
| <b>Tentative Date of Recall Completion</b>  | 31/12/2011  |

|   |                   |
|---|-------------------|
| 1 | WDF63970323459576 |
| 2 | WDF63970523566879 |
| 3 | WDF63981323463723 |
| 4 | WDF63981323465296 |
| 5 | WDF63981323566988 |
| 6 | WDF63981323591923 |
| 7 | WDF63981323601412 |
| 8 | WDF63981323604816 |
| 9 | WDF63981323605135 |

|    |                   |
|----|-------------------|
| 10 | WDF63981323609188 |
| 11 | WDF63970323410888 |
| 12 | WDF63970323413036 |
| 13 | WDF63970323436831 |
| 14 | WDF63970323550528 |
| 15 | WDF63970523398016 |
| 16 | WDF63970523459666 |
| 17 | WDF63970523460210 |
| 18 | WDF63970523545948 |

|    |                   |
|----|-------------------|
| 19 | WDF63981323375252 |
| 20 | WDF63981323383167 |
| 21 | WDF63981323385581 |
| 22 | WDF63981323401386 |
| 23 | WDF63981323404655 |
| 24 | WDF63981323411952 |
| 25 | WDF63981323411962 |
| 26 | WDF63981323412311 |
| 27 | WDF63981323412896 |
| 28 | WDF63981323415566 |
| 29 | WDF63981323417326 |
| 30 | WDF63981323427281 |
| 31 | WDF63981323427591 |
| 32 | WDF63981323428417 |
| 33 | WDF63981323428432 |
| 34 | WDF63981323428845 |
| 35 | WDF63981323429403 |
| 36 | WDF63981323437569 |
| 37 | WDF63981323440197 |
| 38 | WDF63981323440249 |
| 39 | WDF63981323441167 |
| 40 | WDF63981323441216 |
| 41 | WDF63981323448446 |
| 42 | WDF63981323462265 |
| 43 | WDF63981323464544 |
| 44 | WDF63981323464922 |
| 45 | WDF63981323465273 |
| 46 | WDF63981323473705 |
| 47 | WDF63981323486359 |
| 48 | WDF63981323510245 |
| 49 | WDF63981323560172 |
| 50 | WDF63981323561028 |
| 51 | WDF63981323561579 |
| 52 | WDF63981323567166 |
| 53 | WDF63981323573328 |
| 54 | WDF63981323579544 |