Recall Detail	
Ref No	10000364
Manufacturer	Mitsubishi Fuso Truck & Bus Corporation
Vehicle Class	Truck
Model/Type	Canter TF (FB7)
Dealer (phone no)	Sime Darby Motor Services Limited (Tel: 39138800)
Subject	LTD Bevel gear inspection / replacement on TD/TF
Progress	Completed
Affected Vehicle Identification Number (VIN)	Not applicable
Description of Defect, how it came to light, and possible consequences if ignored.	The lock nut of bevel gear could become loose due to lack of tightening torque. If such vehicle is continuously used under such condition, the power steering gear system would be out of order.
Remedial Action	To inspect lock-nut of Power Steering System Bevel Gear if it is loosened. If loosened, to replace it with new one.
<b>Build Dates</b>	2010 - 2011
Launch Date	03/10/2011
Date of Recall Completion	24/11/2011