

Recall Detail

Ref No	10000394
Manufacturer	HINO MOTORS, LTD
Vehicle Class	MGV (Tractor)
Model/Type	SH1EEKA SS1EKKA
Dealer (phone no)	Crown Motors Ltd. (Tel: 28801395)
Subject	Rectify fuel tank & its fixing parts
Progress	Completed
Affected Vehicle Identification Number (VIN)	Completed
Description of Defect, how it came to light, and possible consequences if ignored.	The tightening torque of the “flange nuts” applied during assembly process to fix the fuel tank bands was not proper. If the “flange nuts” become loose, the fuel bands and fuel tank could be damaged
Remedial Action	To replace the relevant parts and then tighten the “flange nuts” with proper tightening torque in accordance with work procedure manual recommended by Hino Motors, Ltd.
Build Dates	Year 2010 to 2011
Launch Date	June 2012
Tentative Date of Recall Completion	Dec 2012