

Recall Detail

| | |
|---|---|
| Ref No | 10000402 |
| Manufacturer | Daimler AG |
| Vehicle Class | Private car |
| Model/Type | E-Class / 211 |
| Dealer (phone no) | Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Kwai Chung Service Centre: 2427 3355 Zung Fu Yuen Long Service Centre: 2473 3171 |
| Subject | Check level sensor linkage at rear axle, replace if necessary (3295037) |
| Progress | Completed |
| Affected Vehicle Identification Number (VIN) | Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2) (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles Remedial action on listed VIN all completed. (2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, please contact Zung Fu Service Centres or us at following telephone numbers to clarify whether your vehicle is affect by this recall (Please notice that this range is for reference use only). |
| Description of Defect, how it came to light, and possible consequences if ignored. | Blocking of the level sensor linkage at the rear axle may possibly occur. This may lead to hardening of the rear-axle suspension and correspondingly to perceptible losses in comfort. |
| Remedial Action | Check the level sensor linkage, and replace it if necessary as a precautionary measure. |
| Build Dates | 07/2006 - 04/2009 |
| Launch Date | 05/10/2012 |
| Tentative Date of Recall Completion | 31/12/2012 |