

Recall Detail

Ref No	10000419
Manufacturer	Mazda Motor Corporate
Vehicle Class	Private car
Model/Type	Mazda6 (GLJ9)
Dealer (phone no)	Vang lek Motors (Hong Kong) Limited 3768 4848
Subject	DC-DC Converter
Progress	Completed
Affected Vehicle Identification Number (VIN)	Not applicable
Description of Defect, how it came to light, and possible consequences if ignored.	A condenser on the electronic substrate of DC-DC converter may have a crack, causing the condenser to short circuit. If this may happen, DC-DC converter may melt and generate smoke in the worst case
Remedial Action	Replace the DC-DC converter with the modified one
Build Dates	25 October 2012 to 8 March 2013
Launch Date	26 March 2013
Date of Recall Completion	10 May 2013