

Recall Detail

Ref No	10000423
Manufacturer	Subaru
Vehicle Class	Private Car
Model/Type	XV
Dealer (phone no)	Motor Image (HK) Ltd (23936118)
Subject	Inspect engine harness
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The recall is due to an engine harness that may have improperly routed during installation and may result in rough idling, engine stalling and the vehicle not being able to restart.
Remedial Action	Routing of the subject engine harness will be inspected and rectified if necessary.
Build Dates	February 2012
Launch Date	25 April 2013
Tentative Date of Recall Completion	31 Dec 2013

1	JF1GP7KC5CG006156
2	JF1GP7KC5CG006269
3	JF1GP7KC5CG006760
4	JF1GP7KC5CG006926
5	JF1GP7KC5CG007442
6	JF1GP7KC5CG007699
7	JF1GP7KC5CG007914
8	JF1GP7KC5CG008167
9	JF1GP7KC5CG008543
10	JF1GP7KC5CG008742