

Recall Detail

Ref No	10000436
Manufacturer	Aston Martin
Vehicle Class	Private Car
Model/Type	DB 9, Rapide / VH1 and V8 Vantage, V12 Zagato / VH2
Dealer (phone no)	MF Jebsen Automotive Limited (2234 0562)
Subject	Throttle Pedal Lever – Incorrect Material Specification
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	It is possible that the throttle pedal lever on these vehicles can fracture. This is because the material that the lever is made from is not to the design specification. If the throttle lever fractures, the throttle will return to the idle position. Loss of function and the failure to change or keep the engine speed above idle speed will occur.
Remedial Action	The throttle pedal assembly must be changed on every vehicle that is in the below VIN listed. Refer to the procedure that follows to change the throttle pedal assembly on the affected vehicles.
Build Dates	Manufactured from May 14 2012 thru April 10 2013
Launch Date	May 29, 2013
Tentative Date of Recall Completion	June 30, 2013