

## Recall Detail

<b>Ref No</b>	<b>10000469</b>
<b>Manufacturer</b>	Brammo
<b>Vehicle Class</b>	Motorcycle
<b>Model/Type</b>	B1
<b>Dealer (phone no)</b>	2624 8899
<b>Subject</b>	Replace Tail Shroud Bracket
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p><b>Description of defect:</b> Mounting bracket in tail assembly can crack and break due to fatigue on Enertia motorcycles with larger registration plate assemblies (such as those used in Hong Kong and EU).</p> <p><b>How it came to light:</b> The defect was first noted by JCAM while servicing an Enertia Plus who then notified Brammo. Upon notification, Brammo started a test program and then reviewed the data. It was found that the mounting brackets are good with smaller registration plates (such as those used in North America), but can fatigue on larger registration plate assemblies due to the increased weight.</p> <p><b>Possible Consequences if ignored:</b> If both sides of the mounting bracket crack and then break the tail assembly could separate from the motorcycle chassis. This could cause an accident if the assembly were to drop onto the rear wheel.</p>
<b>Remedial Action</b>	Brammo has designed and is now testing a new stronger mounting bracket that is expected to fix the issue. The new parts will be issued to JCAM in Hong Kong to install free of charge on all Enertia motorcycles. Brammo will pay for all costs of the repairs.
<b>Build Dates</b>	2009 - 2013
<b>Launch Date</b>	10 April 2014
<b>Tentative Date of Recall Completion</b>	19 June 2014

1	51RUB2136AA000137	COMPLETE
2	51RUB213XAA000075	COMPLETE
3	51RUB21369A000069	COMPLETE
4	51RUB2139AA000149	COMPLETE
5	51RB10006CHA00150	COMPLETE
6	51RB10006CHA00151	COMPLETE
7	51RB10006CHA00152	COMPLETE
8	51RB10006CHA00153	COMPLETE
9	51RB10006CHA00154	COMPLETE
10	51RB10006CHA00155	COMPLETE
11	51RB10006CHA00156	COMPLETE
12	51RB10006CHA00157	COMPLETE
13	51RB10006CHA00158	COMPLETE
14	51RB10006CHA00159	COMPLETE

15	51RB10006CHA00160	COMPLETE
16	51RB10206DHA00163	COMPLETE
17	51RB10206DHA00165	COMPLETE
18	51RB10206DHA00170	COMPLETE
19	51RB10206DHA00057	COMPLETE
20	51RB10206DHA00058	COMPLETE
21	51RB10206DHE00194	COMPLETE
22		
23		
24		
25		
26		
27		
28		