

Recall Detail

Ref No	10000481
Manufacturer	Aston Martin
Vehicle Class	Private Car
Model/Type	DB9 Coupe, DB9 Volante, Rapide, Rapide S
Dealer (phone no)	MF Jebsen Automotive Limited (2234 0562)
Subject	Replacement of Transmission Control Switches
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	<p>It is possible that, when operated, the transmission control switches (PRND push button switches) in the instrument panel of your vehicle can internally short-circuit. This is because it is possible that the printed circuit boards (PCBs) inside the switches are defective.</p> <p>If this occurs, the transmission can change to a neutral gear without any driver input. This can cause a loss of drive and the driver will be unable to maintain or increase the car's speed. If this does occur, there will be no effect on the power steering and braking systems. It is possible that drive can be restored if you safely stop and start the vehicle again.</p>
Remedial Action	We will replace the transmission control switches ("PRND" pushbuttons) free of charge with quality assured parts to the correct design specification.
Build Dates	Manufactured from June 2013 To July 2014
Launch Date	18 July 2014
Tentative Date of Recall Completion	17 July 2015