

Recall Detail

Ref No	10000482
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	SLK-Class, SL-Class / R172, R231
Dealer (phone no)	Aberdeen Service Centre: 2552 8298 Quarry Bay Service Centre: 2563 4333 Hunghom Service Centre: 2363 9396 Kwai Chung Service Centre: 2427 3355 Yuen Long Service Centre: 2473 3171
Subject	Replace front passenger front airbag module (9193042)
Progress	Completed
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres or us at above mentioned telephone numbers to clarify whether your vehicle is affect by this recall.
Description of Defect, how it came to light, and possible consequences if ignored.	As part of constant product monitoring, we found that it is possible that a front passenger front airbag module was installed on your vehicle that does not correspond to the specifications.
Remedial Action	Replace the front passenger front airbag module as a precautionary measure.
Build Dates	3/2014 - 5/2014
Launch Date	01/08/2014
Tentative Date of Recall Completion	31/12/2014