

Recall Detail

Ref No	10000524
Manufacturer	Volvo
Vehicle Class	Medium and Heavy Goods Vehicle
Model/Type	FM and FH
Dealer (phone no)	International Automobiles Limited (3713 1788)
Subject	Replacement of tilt cylinder lower bolt
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The lower attachment bolt of cab might have been over torqued and become stretch, which could cause a breakage of the bolt and the cab might fall back
Remedial Action	Replace the tilt cylinder lower bolt
Build Dates	2014 - 2015
Launch Date	Jun-2015
Tentative Date of Recall Completion	Dec-2015

1	YV2X1F1A1EA769362
2	YV2RG20C2EA769390
3	YV2X1E1C2EA769396
4	YV2X1F1F9EA769654
5	YV2X1E1C6FA770259
6	YV2X1E1CXFA770720
7	YV2X1E1C5FA771161
8	YV2X1F1A0FA772013
9	YV2X1F1A2FA772031
10	YV2X1F1A7FA772235
11	YV2X1F1G5FA772254
12	YV2XG20G1FA775113
13	
14	
15	
16	
17	
18	
19	
20	

21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	