

Recall Detail

Ref No	10000547
Manufacturer	Volvo
Vehicle Class	Medium and Heavy Goods Vehicle
Model/Type	FM and FH
Dealer (phone no)	International Automobiles Limited (3713 1788)
Subject	Check U-bolts on the front axle are tightened
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The front axle could have too low torque on the front axle screws/nuts, which can lead to that the screws/nuts holding the front axle could become loose.
Remedial Action	Check that the U-bolts on the front axle are tightened with correct torque
Build Dates	2014-2015
Launch Date	5 Aug 2015
Tentative Date of Recall Completion	Oct-2016

1	YV2X1E1C7FA772361
2	YV2X1E1C2FA772428
3	YV2X1E1C5FA772438
4	YV2X1E1C9FA772443
5	YV2XG20G2FA772446
6	YV2X1E1C8FA772448
7	YV2X1E1C1FA772453
8	YV2X1E1C9FA772460
9	YV2X1E1C6FA772464
10	YV2XG20GXFA772467
11	YV2X1E1C4FA772494
12	YV2X1E1CXFA772516
13	YV2X1E1C6FA772531
14	YV2X1E1C5FA772939
15	YV2RG20C4FA773930
16	YV2X1E1C9FA777044
17	
18	
19	

20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	