

Recall Detail

Ref No	10000550
Manufacturer	UD
Vehicle Class	Medium and Heavy Goods Vehicle
Model/Type	CWB5E
Dealer (phone no)	International Automobiles Limited (3713 1788)
Subject	Replace propeller shaft assembly.
Progress	Running
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	There is a crack in propeller shaft splined yoke which may lead parts drop off from chassis and unplanned stop.
Remedial Action	UD requires that all vehicles identified in this document need to replace propeller shaft assembly.
Build Dates	2014-2015
Launch Date	11 Sep 2015
Tentative Date of Recall Completion	Until complete

1	CWB5E00566
2	CWB5E00571
3	CWB5E00578
4	CWB5E00586
5	CWB5E00567
6	CWB5E00572
7	CWB5E00579
8	CWB5E00587
9	CWB5E00568
10	CWB5E00574
11	CWB5E00581
12	CWB5E00588
13	CWB5E00569
14	CWB5E00575
15	CWB5E00583
16	CWB5E00592
17	CWB5E00570
18	CWB5E00576
19	

20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	