

## Recall Detail

<b>Ref No</b>	<b>10000554</b>
<b>Manufacturer</b>	Hino
<b>Vehicle Class</b>	Light Goods Vehicle & Medium Goods Vehicle
<b>Model/Type</b>	300 Series LGV : XKU640R-HKUMS3, XKU710R-HKUQSQ3, XKU710R-HKUQS3, XZU700R-HKFQT3, XZU710R-HKFQT3, XZU710R-HKTQS3, XZU710R-QKFQT3, XZU720R-HKFQT3, XZU720R-HKTQS3,  MGV : XKU720R-HKUTS3, XKU730R-HKUTS3, XZU720R-HKFTT3, XZU730R-HKFTT3
<b>Dealer (phone no)</b>	2820 5000
<b>Subject</b>	Recall Campaign for Engine Fuel Filter on Hino 300 Series
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Due to repeated changes of fuel pressure in engine fuel filter by frequently start & stop of engine. The engine fuel filter may crack and resulting in fuel leakage.
<b>Remedial Action</b>	To replace enhanced engine fuel filter in accordance with work procedure recommended by Hino Motors, Ltd.
<b>Build Dates</b>	Jan 2011 to Jan 2014
<b>Launch Date</b>	October 2015
<b>Tentative Date of Recall Completion</b>	December 2016

1	JHHYCT3H90K001002
2	JHHYCS3H40K001001
3	JHHZCT2HX0K001001
4	JHHTCT3H60K001002
5	JHHUCT3H00K001002
6	JHHYCT2H90K001003
7	JHHUCS3H10K001004
8	JHHMCT3H60K001005
9	
10	
11	

12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	