

Recall Detail

Ref No	10000559
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	CLA-Class, GLA-Class, A-Class and B-Class with M270; SLK-Class, C-Class and E-Class with M274 / 117, 156, 176, 242 and 246 with M270; 172, 205, 207 and 212 with M274
Dealer (phone no)	Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Kwai Chung Service Centre: 2427 3355 Zung Fu Yuen Long Service Centre: 2473 3171
Subject	Replace exhaust camshaft (0590034)
Progress	Completed
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2): (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles. 2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.
Description of Defect, how it came to light, and possible consequences if ignored.	Fault in the welding process performed by the supplier, the weld seam at the camshaft may not be performing properly on individual M270 and M274 four-cylinder gasoline engines. In the affected vehicles, the camshafts could break, damage and shut off the engine, and as a result, the engine cannot be restarted and the vehicle will remain immobile, which eventually increase the accident hazard.
Remedial Action	Replace the camshafts on affected vehicle as a precautionary measure.
Build Dates	07/2015 - 09/2015
Launch Date	11/11/2015
Tentative Date of Recall Completion	31/12/2016

