

Recall Detail

Ref No	10000581
Manufacturer	Subaru
Vehicle Class	Private Car
Model/Type	SUBARU IMPREZA / XV
Dealer (phone no)	Motor Image Kowloon Limited (23936118)
Subject	Software update for Engine Control Module (ECM)
Progress	Completed
Affected Vehicle Identification Number (VIN)	List as below:
Description of Defect, how it came to light, and possible consequences if ignored.	The recall is due to an Engine Control Module (ECM) software problem and may result the noise heard from the engine is being started and the engine subsequently fails to start.
Remedial Action	Update ECM software.
Build Dates	February 2015
Launch Date	11 April 2016
Tentative Date of Recall Completion	31 December 2017

1	JF1GP7KC5FG151085
2	JF1GP7KC5FG151100
3	JF1GP7KC5FG151107
4	JF1GP7KC5FG151123
5	JF1GP7KC5FG151126
6	JF1GP7KC5FG152741
7	JF1GP7KC5FG152793
8	JF1GP7KC5FG152863
9	JF1GP7KC5FG152867
10	JF1GP7KC5FG152917
11	JF1GP7KC5FG157035
12	JF1GP7KC5FG157097
13	JF1GP7KC5FG157105
14	JF1GP7KC5FG157122