

## Recall Detail

<b>Ref No</b>	<b>10000655</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	C-Class, E-Coupe, E-Class and S-Class / 205, 207, 212 and 222
<b>Dealer (phone no)</b>	Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Kwai Chung Service Centre: 2427 3355 Zung Fu Yuen Long Service Centre: 2473 3171
<b>Subject</b>	Replace electric power steering (4694134)
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	Remedial action on affected vehicles all completed.
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>On affected vehicles a permanent electrical connection in the control unit for the electric power steering cannot be ensured. As a consequence, power steering assistance may fail.</p> <p>This leads to an increased accident hazard. Under certain circumstances, in case of an interruption of the electrical connection, it cannot be ruled out that this leads to a fire.</p>
<b>Remedial Action</b>	Replace the electric steering on affected vehicles as a precautionary measure.
<b>Build Dates</b>	C-Class : 16/06/2014 E-Coupe : 06/08/2015 E-Class : 06/02/2015 S-Class : 20/11/2013
<b>Launch Date</b>	14/02/2017
<b>Tentative Date of Recall Completion</b>	31/12/2017