

## Recall Detail

<b>Ref No</b>	<b>10000674</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	smart fortwo / 453
<b>Dealer (phone no)</b>	Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Yuen Long Service Centre: 2473 3171
<b>Subject</b>	Perform programming and SCN coding in multimedia system (5490437)
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	The "MirrorLink™" function is activated. A connection between a mobile phone and the vehicle's multimedia system can be established with this function. The contents of the mobile phone (e.g. text messages, photos, etc.) can be displayed on the multimedia system display in the vehicle. The display of photos, videos and text messages is not permitted under legislation both while the vehicle is driving and when it is at a standstill.
<b>Remedial Action</b>	Recode the control unit of the multimedia system on affected vehicles as a measure.
<b>Build Dates</b>	02/07/2015 - 25/02/2016
<b>Launch Date</b>	21/03/2017
<b>Tentative Date of Recall Completion</b>	31/12/2017