

## Recall Detail

<b>Ref No</b>	<b>10000691</b>
<b>Manufacturer</b>	Volvo
<b>Vehicle Class</b>	Medium Goods Vehicle
<b>Model/Type</b>	FL
<b>Dealer (phone no)</b>	International Automobiles Limited (3713 1788)
<b>Subject</b>	Rear axle, suspension, screw, check.
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	Risk for loss of tension in the rear axle suspension assembly (i.e. nut could lose its torque and cause a screw breakage).
<b>Remedial Action</b>	Inspect the suspension installation and tighten torque or replace parts if needed.
<b>Build Dates</b>	2015-2016
<b>Launch Date</b>	10 May 2017
<b>Tentative Date of Recall Completion</b>	30 Apr 2018

1	YV2TH60A0FZ102359
2	YV2TH60A0FZ102362
3	YV2TH60A0FZ102569
4	YV2TH60A0FZ102572
5	YV2TH60A0FZ102586
6	YV2TH60A0FZ104032
7	YV2TH60A0GZ104808
8	YV2TH60A0GZ105408
9	YV2TH60A0GZ105893
10	YV2TH60A1GZ105868
11	YV2TH60A2FZ102377
12	YV2TH60A2GZ105894
13	YV2TH60A3FZ102100
14	YV2TH60A3FZ103697
15	YV2TH60A3GZ105435
16	YV2TH60A5FZ103717
17	YV2TH60A6FZ102088
18	YV2TH60A6GZ105400
19	YV2TH60A6GZ105431

20	YV2TH60A6GZ105896
21	YV2TH60A7FZ102570
22	YV2TH60A7FZ104044
23	YV2TH60A8FZ102383
24	YV2TH60A9FZ104045
25	YV2TH60A9GZ105407
26	YV2TH60AXGZ104654
27	YV2TH60AXGZ105870
28	YV2TN12A1GZ108214
29	YV2TN12A2GZ108240
30	YV2TN12A4FZ104043
31	YV2TN12A6FZ104335
32	YV2TN12A6GZ107799
33	YV2TN12A6GZ107804
34	YV2TN12A6GZ107835
35	YV2TN12AXFZ104290
36	YV2TN12AXGZ108261