

Recall Detail

| | |
|---|---|
| Ref No | 10000696 |
| Manufacturer | Daimler AG |
| Vehicle Class | Private car |
| Model/Type | GLA, A-Class & B-Class/ 156, 176 & 246 |
| Dealer (phone no) | Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Kwai Chung Service Centre: 2427 3355 Zung Fu Yuen Long Service Centre: 2473 3171 |
| Subject | Replacement of front passenger airbag (9192150) |
| Progress | Completed |
| Affected Vehicle Identification Number (VIN) | <p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p> |
| Description of Defect, how it came to light, and possible consequences if ignored. | <p>The propellant mixing ratio in the squid of the front passenger airbag in affected vehicles may not meet the specifications. In the event of an accident triggering a front passenger airbag, this may not be deployed or only partially so.</p> <p>As a result, the restraint effect of the front passenger airbag could not be guaranteed. This could increase the risk of injury to the occupants.</p> |
| Remedial Action | Replace the front passenger airbag on affected vehicles as a precautionary measure. |
| Build Dates | GLA: 17/08/2016 - 22/08/2016 A-Class: 18/08/2016 B-Class: 16/08/2016 - 23/08/2016 |
| Launch Date | 06/06/2017 |
| Tentative Date of Recall Completion | 31/12/2017 |

