

Recall Detail

Ref No	10000729
Manufacturer	Daimler AG
Vehicle Class	Heavy Goods Vehicle
Model/Type	Actros & Antos
Dealer (phone no)	Zung Fu Commercial Vehicle Service Centre: 2637 2988
Subject	Visual inspection of rear axle (3592556)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centre at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>Possibly minor oil leakages up to fracture of axle housings could happen at the rear axles on affected vehicles.</p> <p>An axle housing fracture could increase the risk of an accident occurring.</p>
Remedial Action	Carry out a precautionary visual inspection of the rear axle housing of affected vehicles and replace the rear axle, if necessary.
Build Dates	25/07/2013 - 12/03/2016
Launch Date	12/09/2017
Tentative Date of Recall Completion	31/12/2017