

Recall Detail

Ref No	10000739
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	S-Class / 222
Dealer (phone no)	Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Yuen Long Service Centre: 2473 3171
Subject	Replace seat belt for right front seat (9190201)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The propellant mixing ratio of certain seat belt tensioner squibs in affected vehicles may not meet the specifications.</p> <p>In the event of an accident triggering the front right belt tensioner, it may not be able to be deployed.</p> <p>Consequently the retaining effect of this belt tensioner would not be guaranteed. This could increase the risk of injury to the occupants.</p>
Remedial Action	Replace the seat belt for the right front seat in affected vehicles as a precautionary measure.
Build Dates	08/04/2015 - 24/10/2016
Launch Date	07/09/2017
Tentative Date of Recall Completion	30/04/2018

1	WDD2221651A302028
2	WDD2221652A305757
3	WDD2221822A184119
4	WDD2221822A304912