

## Recall Detail

<b>Ref No</b>	<b>10000743</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Light Goods Vehicle (Van)
<b>Model/Type</b>	Vito / 447
<b>Dealer (phone no)</b>	Zung Fu Commercial Vehicle Service Centre: 2637 2988
<b>Subject</b>	Check retaining rings of left and right front axle wheel bearings (3392086)
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	<p>The retaining rings of the wheel bearings on the front axle may not be correctly engaged in certain VITO vehicles. The position of these retaining rings and as a result the wheel bearings may change.</p> <p>An ABS warning display in the instrument cluster as well as clearly discernible service brake noises would draw the driver's attention to a problem present in the vehicle.</p> <p>If the indicated early warning signs are disregarded, wheel loss can in the most unfavorable case not be excluded. This may increase the risk of accident and thus the risk of injury for the occupants.</p>
<b>Remedial Action</b>	Check the retaining rings on the wheel bearings of the front axle for correct positioning and if necessary correct the position.
<b>Build Dates</b>	13/06/2017 - 21/06/2017
<b>Launch Date</b>	30/11/2017
<b>Tentative Date of Recall Completion</b>	31/04/2018