

Recall Detail

Ref No	10000765
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	AMG GT R/C/S / 190
Dealer (phone no)	Zung Fu Aberdeen Service Centre: 2552 8298 Zung Fu Quarry Bay Service Centre: 2563 4333 Zung Fu Hunghom Service Centre: 2363 9396 Zung Fu Yuen Long Service Centre: 2473 3171
Subject	Rework seat belt guide loop (9193138)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>It is possible that a seat belt on affected vehicle may jam in the seat belt guide loop.</p> <p>This could impair the restraint effect of the seat belt. As a result, the risk of injuries to the occupants could increase.</p>
Remedial Action	Rework the seat belt guide loop on affected vehicle as a precautionary measure.
Build Dates	09/05/2017 - 27/10/2017
Launch Date	26/03/2018
Tentative Date of Recall Completion	31/12/2018