

Recall Detail

Ref No	10000808
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	S-Class / 222
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Quarry Bay Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Check rear prefuse box, replace if necessary (5497631)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>it is possible that two nuts for mounting busbars in the prefuse box located in affected vehicle's trunk were not installed.</p> <p>This could increase transitional resistances between the busbars and thus present a fire hazard. In addition, the interruption of electrical contact of the busbars may lead to function failures. The running of engine, belt functions and the instrument cluster could be among the components impaired, which may increase the danger of an accident and potentially also the risk of injury in the event of an accident.</p>
Remedial Action	Check the rear prefuse box on affected vehicles as a precautionary measure and replace it if necessary.
Build Dates	07/09/2017 - 09/11/2017
Launch Date	09/08/2018
Tentative Date of Recall Completion	31/12/2018

3	WDD2221622A365296
4	WDD2221622A365448
5	WDD2221622A365930
6	WDD2221622A366604
7	WDD2221622A366895
8	WDD2221622A367023
9	WDD2221622A367128
10	WDD2221622A367561
11	WDD2221622A367905
12	WDD2221622A368041
13	WDD2221622A368400
14	WDD2221622A369081
15	WDD2221622A369119
16	WDD2221622A369194
17	WDD2221622A369305
18	WDD2221622A369365
19	WDD2221622A369415
20	WDD2221622A369419
21	WDD2221622A369663
22	WDD2221622A369665
23	WDD2221622A370168
24	WDD2221622A370565
25	WDD2221622A370664
26	WDD2221622A371527
27	WDD2221622A374529
28	WDD2221622A374660
29	WDD2221622A374730
30	WDD2221622A374817
31	WDD2221622A374855
32	WDD2221622A374965
33	WDD2221622A375065
34	WDD2221622A375233
35	WDD2221622A378314
36	WDD2221622A378715
37	WDD2221622A379788
38	WDD2229802A367491
39	WDD2229802A373450
40	WDD2229832A367282
41	WDD2229832A367325
42	WDD2229832A367355

43	WDD2229832A370649
44	WDD2229832A370855
45	WDD2229832A371009
46	WDD2229832A371090
47	WDD2229832A371093
48	WDD2229832A371301
49	WDD2229832A371333
50	WDD2229832A371459
51	WDD2229832A371699
52	WDD2229832A373511
53	WDD2229832A375275
54	WDD2229832A378781
55	WDD2229832A378834
56	WDD2229832A379525
57	WDD2229832A379536