

Recall Detail

Ref No	10000812
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	GLA-Class, A-Class, B-Class, C-Class & GLC-Class / 156, 176, 246, 205 & 253
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Quarry Bay Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Replace driver's airbag (9193142)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The housing material of the gas generator in the driver's airbag of affected vehicles may not correspond to the specifications.</p> <p>If the material of the gas generator housing fails, the airbag might not have a restraint effect if the driver's airbag were triggered in the event of a crash. Additionally, separating parts could enter the passenger compartment. This could lead to an increased risk of injury.</p>
Remedial Action	Replace the driver's airbag in affected vehicles as a precautionary measure.
Build Dates	24/01/2018 - 06/02/2018
Launch Date	10/07/2018
Tentative Date of Recall Completion	31/12/2018

