

## Recall Detail

<b>Ref No</b>	<b>10000858</b>
<b>Manufacturer</b>	Daimler AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	GLC-Class / 253
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
<b>Subject</b>	Replace electric power steering (4693002)
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	A sensor for the electric power steering on affected vehicles may have been manufactured outside of the specification.  If the sensor were to fail, it is possible that the steering power assistance would be disabled, which would increase the danger of an accident.
<b>Remedial Action</b>	Replace the electric power steering on affected vehicles as a precautionary measure.
<b>Build Dates</b>	13/07/2018 - 30/07/2018
<b>Launch Date</b>	09/04/2019
<b>Tentative Date of Recall Completion</b>	31/12/2019