

Recall Detail

Ref No	10000880
Manufacturer	Daimler AG
Vehicle Class	Private car
Model/Type	CLA, A-Class / 118, 177
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Hung Hom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Threaded connection of driver's airbag (9192105)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affected by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The four lock nuts for fastening the airbag may not have been screwed in affected vehicles. In the event of an accident in which the airbag is deployed, the airbag may detach itself from its base plate and enter into the vehicle interior at high speed.</p> <p>As a result, the restraint effect of the airbag may not be ensured and the risk of injury for the occupants may be increased.</p>
Remedial Action	Check the driver's airbag in affected vehicles as a precautionary measure and exchange it if necessary.
Build Dates	29/12/2018 - 16/9/2019
Launch Date	08/10/2019
Tentative Date of Recall Completion	31/12/2019