

## Recall Detail

<b>Ref No</b>	<b>10000886</b>
<b>Manufacturer</b>	Toyota
<b>Vehicle Class</b>	Private Car
<b>Model/Type</b>	Sienta HV / Prius C
<b>Dealer (phone no)</b>	Crown Motors Limited (Tel: 2880 4988)
<b>Subject</b>	DC/DC converter
<b>Progress</b>	<b>Running</b>
<b>Affected Vehicle Identification Number (VIN)</b>	List as below:
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	A component may stop performing its function of converting power from the hybrid vehicle battery for use by certain vehicle systems. If this occurs, a series of warning lights will illuminate, audible chimes will sound, and messages will be displayed on the instrument panel. If the vehicle continues to be operated, it could lose motive power.
<b>Remedial Action</b>	Inspect and, if necessary, replace the DC/DC converter
<b>Build Dates</b>	Prius C: Feb 2018 ~ May 2018 Sienta HV: Feb 2018 ~ Sep 2018
<b>Launch Date</b>	October 2019
<b>Tentative Date of Recall Completion</b>	December 2020

1	JTDKD3B3101611977
2	JTDKD3B3701612129
3	JTDKD3B3501612307
4	JTDKD3B3601612235
5	JTDKD3B3X01612352
6	JTDKD3B3X01614523
7	JTDKD3B3701616598
8	JTDZZ9H3X0L000523
9	JTDZZ9H370L000530
10	JTDZZ9H310L000538
11	JTDZZ9H370L000544
12	JTDZZ9H350L000557
13	JTDZZ9H3X0L000554
14	JTDZZ9H370L000558
15	JTDZZ9H390L000559
16	JTDZZ9H300L000563