

Recall Detail

Ref No	10000982
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	GLA & AMG A35 4MATIC / 156 & 177
Dealer (phone no)	Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140
Subject	Threaded connection for control unit box (5494022)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date falls into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>The threaded connection of the control unit box in the engine compartment in affected vehicles may not correspond with the specification. As a result, contact separations cannot be excluded; these could, among other things, cause a loss of propulsive power due to engine stop as well as a failure of the power steering, ESP or the Active Brake Assist.</p> <p>In this case, the risk of an accident would be increased.</p>
Remedial Action	Check the threaded connection in affected vehicles as a precautionary measure and correct if necessary.
Build Dates	21/05/2019 - 23/05/2019
Launch Date	16/11/2020
Tentative Date of Recall Completion	31/03/2021