

Recall Detail

Ref No	10000990
Manufacturer	Daimler AG
Vehicle Class	Heavy Goods Vehicle
Model/Type	Actros, Antos and Atego / 963 & 967
Dealer (phone no)	Zung Fu Commercial Vehicle Service Centre: 2111 7428
Subject	Replace airbag (9193168)
Progress	Completed
Affected Vehicle Identification Number (VIN)	Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):
	<p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centre at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall</p>
Description of Defect, how it came to light, and possible consequences if ignored.	<p>Our supplier TK Holdings, Inc. ("Takata"), has informed us that specific climatic conditions may cause a chemical change to the propellant in the gas generator of the Takata airbag over time.</p> <p>For this reason we are carrying out a worldwide recall as a precautionary measure.</p>
Remedial Action	Replace affected vehicle's airbag as part of this recall.
Build Dates	06/05/2013 - 20/07/2017
Launch Date	17/12/2020
Tentative Date of Recall Completion	30/06/2021

1	WDB96302020020417
2	WDB96302520050390
3	WDB96340320153307
4	WDB96340320153308
5	WDB96340320153309
6	WDB96340320186790
7	WDB9634032L771165

8	WDB9634032L771166
9	WDB9634032L771167
10	WDB9634032L851483
11	WDB9634032L958544
12	WDB96342520050443
13	WDB9634252L760960
14	WDB9634252L824370

15	WDB9670042L994125
16	WDB96760520144869
17	WDB96760520144870