Ref No Manufacturer Mercedes-Benz AG Vehicle Class Model/Type GLA 200 / 247 Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140 Subject Progress Completed Regarding the chassis number of vehicle affected by this campaign , please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identification Number (VIN)  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.  The ground connection of the front passenger airbag in affected vehicles may not correspond to the specifications. In this case, an electrostatic charge could not be diverted via the ground connection of the front passenger airbag. A random inflation of the front passenger airbag could also not be ruled out when using a child seat on the front passenger seat with a properly deactivated front passenger airbag.	Recall Detail		
Vehicle Class Model/Type GLA 200 / 247 Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140 Subject Progress Completed Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.  The ground connection of the front passenger airbag in affected vehicles may not correspond to the specifications. In this case, an electrostatic charge could not be diverted via the ground connection of the front passenger airbag as intended.  This could lead to a random inflation of the front passenger airbag could also not be ruled out when using a child seat on the front passenger seat with a properly deactivated front passenger airbag.	Ref No	10000997	
Dealer (phone no)  Completed  Affected Vehicle Identification Number (VIN)  Description of Defect, how it came to light, and possible consequences if ignored.  Chai Wan Service Centre: 2504 6140  Hunghom Service Centre: 2504 6140  Yuen Long Service Centre: 2504 6140  Front passenger airbag ground connection (9193003)  Completed  Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.  The ground connection of the front passenger airbag in affected vehicles may not correspond to the specifications. In this case, an electrostatic charge could not be diverted via the ground connection of the front passenger airbag.  A random inflation of the front passenger airbag could also not be ruled out when using a child seat on the front passenger seat with a properly deactivated front passenger airbag.	Manufacturer	Mercedes-Benz AG	
Chai Wan Service Centre: 2504 6140 Hunghom Service Centre: 2504 6140 Yuen Long Fu Service Centre: 2504 6140 Yuen Long Service Centre: 2504	Vehicle Class	Private car	
Hunghom Service Centre: 2504 6140	Model/Type	GLA 200 / 247	
Progress  Completed  Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.  The ground connection of the front passenger airbag in affected vehicles may not correspond to the specifications. In this case, an electrostatic charge could not be diverted via the ground connection of the front passenger airbag as intended.  This could lead to a random inflation of the front passenger airbag could also not be ruled out when using a child seat on the front passenger seat with a properly deactivated front passenger airbag.	. ,	Hunghom Service Centre: 2504 6140 Yuen Long Service Centre: 2504 6140	
Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):  (1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.  The ground connection of the front passenger airbag in affected vehicles may not correspond to the specifications. In this case, an electrostatic charge could not be diverted via the ground connection of the front passenger airbag as intended.  This could lead to a random inflation of the front passenger airbag. A random inflation of the front passenger airbag could also not be ruled out when using a child seat on the front passenger seat with a properly deactivated front passenger airbag.	-		
Affected Vehicle Identification Number (VIN)  2) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.  2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.  The ground connection of the front passenger airbag in affected vehicles may not correspond to the specifications. In this case, an electrostatic charge could not be diverted via the ground connection of the front passenger airbag as intended.  This could lead to a random inflation of the front passenger airbag. A random inflation of the front passenger airbag could also not be ruled out when using a child seat on the front passenger seat with a properly deactivated front passenger airbag.	Progress	•	
Description of Defect, how it came to light, and possible consequences if ignored.  vehicles may not correspond to the specifications. In this case, an electrostatic charge could not be diverted via the ground connection of the front passenger airbag as intended.  This could lead to a random inflation of the front passenger airbag. A random inflation of the front passenger airbag could also not be ruled out when using a child seat on the front passenger seat with a properly deactivated front passenger airbag.	<b>Identification Number</b>	<ul> <li>campaign, please refer to EITHER (1) or (2):</li> <li>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</li> <li>2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fells into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800)</li> </ul>	
injury.	how it came to light, and possible consequences if	vehicles may not correspond to the specifications. In this case, an electrostatic charge could not be diverted via the ground connection of the front passenger airbag as intended.  This could lead to a random inflation of the front passenger airbag. A random inflation of the front passenger airbag could also not be ruled out when using a child seat on the front passenger seat with a properly deactivated front passenger airbag.  As a result, this would increase the risk of an accident and/or	
Check the ground connection of the front passenger airbag in affected vehicles as a precautionary measure and correct it if necessary.	Remedial Action	Check the ground connection of the front passenger airbag in affected vehicles as a precautionary measure and correct it if	
Build Dates 02/06/2020 - 06/07/2020	<b>Build Dates</b>	,	

Launch Date	26/02/2021
Tentative Date of Recall Completion	30/06/2021

1	W1N2477872J136112
2	W1N2477872J140262
3	W1N2477872J144410
4	W1N2477872J144455
5	W1N2477872J144486
6	W1N2477872J144586
7	W1N2477872J144604
8	W1N2477872J144606
9	W1N2477872J144617
10	W1N2477872J144960
11	W1N2477872J145074
12	W1N2477872J145788
13	W1N2477872J145903