

Recall Detail

Ref No	10001052
Manufacturer	Mercedes-Benz AG
Vehicle Class	Light Goods Vehicle (Van)
Model/Type	Sprinter 907.641
Dealer (phone no)	Fanling Commercial Vehicle Service Centre: 2637 2988 Lau Fau Shan Commercial Vehicle Service Centre: 2111 7428
Subject	Replace brake calipers at rear axle (4296093)
Progress	Completed
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	We have found that in certain vehicles equipped with an electric parking brake, system-internal leakage of minimal amounts of brake fluid may occur at the rear axle brake caliper with advanced operating time and a high number of parking brake actuations. As a result, air may enter into the brake system in the opposite direction. This could lead to increasingly extended brake pedal travel and an altered brake pedal feel.
Remedial Action	As a precautionary measure, to check the fill level in the brake fluid reservoir, replace the brake calipers at the rear axle, and update the software of the ESP control unit on the affected vehicles.
Build Dates	04/06/2019 – 28/06/2019
Launch Date	25/02/2022
Tentative Date of Recall Completion	31/12/2022

1

WDB9076412P134518

3

WDB9076412P134809

2

WDB9076412P134808

4

WDB9076412P136580

5	WDB9076412P137948
6	WDB9076412P138184
7	WDB9076412P138616
8	WDB9076412P143595
9	WDB9076412P144124
10	WDB9076412P144125
11	WDB9076412P144126
12	WDB9076412P144482