

Recall Detail

Ref No	10001054
Manufacturer	Mercedes-Benz AG
Vehicle Class	Private car
Model/Type	S-Class/ 223
Dealer (phone no)	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
Subject	Rear Airbag Actuation (9193114)
Progress	Running
Affected Vehicle Identification Number (VIN)	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8800) to clarify whether your vehicle is affect by this recall.</p>
Description of Defect, how it came to light, and possible consequences if ignored.	The wiring of the left and right rear airbags could be interchanged on certain right hand drive S-Class (223 platform) vehicles. Depending on the seat occupation, each rear airbag can be activated or deactivated manually. As a result, the airbag on the other side of the vehicle would erroneously be switched on or off. This could increase the risk of injury to rear occupants in case of a crash.
Remedial Action	As a precautionary measure, to rework on the wiring harness in the affected vehicles.
Build Dates	08/09/2020 – 02/12/2020
Launch Date	15/03/2022
Tentative Date of Recall Completion	31/12/2022

1	W1K2231612A016039
2	W1K2231612A016277
3	W1K2231612A016393
4	W1K2231612A016399
5	W1K2231612A016491

6	W1K2231612A016500
7	W1K2231632A003008
8	W1K2231632A012828
9	W1K2231632A013090
10	W1K2231632A013137

11	W1K2231632A013283
12	W1K2231632A013665
13	W1K2231632A013918
14	W1K2231632A013953
15	W1K2231632A014721
16	W1K2231632A014770
17	W1K2231632A014963
18	W1K2231632A016090
19	W1K2231632A016272
20	W1K2231632A016321
21	W1K2231632A016381
22	W1K2231632A016550
23	W1K2231632A017530