

## Recall Detail

<b>Ref No</b>	<b>10001131</b>
<b>Manufacturer</b>	Mercedes-Benz AG
<b>Vehicle Class</b>	Private car
<b>Model/Type</b>	A-Class/ 177
<b>Dealer (phone no)</b>	Chai Wan Service Centre: 2895 7323 Hung Hom Service Centre: 2363 9396 Yuen Long Service Centre: 2473 3171
<b>Subject</b>	Vulcanization of tires (4092218)
<b>Progress</b>	<b>Completed</b>
<b>Affected Vehicle Identification Number (VIN)</b>	<p>Regarding the chassis number of vehicle affected by this campaign, please refer to EITHER (1) or (2):</p> <p>(1) If vehicle was bought from Zung Fu or ever repaired under warranty in Zung Fu Service Centre, please see below the list of chassis numbers of identified and remaining vehicles.</p> <p>(2) If vehicle was not bought from Zung Fu and never repaired under warranty in Zung Fu Service Centre, and the vehicle production date fell into that specified in "Build date", please contact Zung Fu Service Centres at above mentioned telephone numbers, or Mercedes-Benz Hong Kong Limited (Tel: 2594 8183) to clarify whether your vehicle is affected by this recall.</p>
<b>Description of Defect, how it came to light, and possible consequences if ignored.</b>	We have determined on certain vehicles that the tires unfortunately might not meet the load requirements. In this case, damage to the tire carcass can occur while driving. As a result, the tire could lose air pressure or the tire-tread could detach partially or completely. Thus, the risk of a crash or injury could be increased.
<b>Remedial Action</b>	As a precautionary measure, to check the tires on the affected vehicles and replace it where necessary.
<b>Build Dates</b>	31/05/2022 – 29/07/2022
<b>Launch Date</b>	26/06/2023
<b>Tentative Date of Recall Completion</b>	30/06/2024

1	W1K1770842V147154
2	W1K1770842V147318
3	W1K1770842V147351
4	W1K1770842V147368

5	W1K1770842V147395
6	W1K1770842V147530
7	W1K1770842V147545
8	W1K1770842V149029

9	W1K1770842V149041
10	W1K1770842V149090
11	W1K1770842V149159
12	W1K1770842V149187
13	W1K1770842V149213
14	W1K1770842V149240
15	W1K1770842V149279
16	W1K1770842V149505