

| Recall Detail | |
|--|---|
| Ref No. | 10001132 |
| Manufacturer | Jaguar |
| Vehicle Class | M1 – Private Car |
| Model/Type | I-Pace (DH) |
| Dealer (phone no. / e-mail) | British Motors Limited - (Tel: 2821 7100 or 2820 5150 / info@jaguar.com.hk) |
| Subject | Battery Energy Control Module (BECM) software update |
| Progress | Completed |
| Affected Vehicle Identification Number (VIN) | List as below: |
| Description of Defect, how it came to light, and possible consequences if ignored. | Some vehicles have experienced thermal overload which may show as smoke or fire, which may occur underneath the vehicle where the High Voltage (HV) battery is located. |
| Remedial Action | Update the Battery Energy Control Module (BECM) software |
| Build Dates | 2019 to 2022 |
| Launch Date | 19 Jun 2023 |
| Tentative Date of Recall Completion | 31 December 2026 |

| | |
|-----|-------------------|
| 1. | SADHA2A10L1F85199 |
| 2. | SADHA2A11K1F72461 |
| 3. | SADHA2A11L1F84529 |
| 4. | SADHA2A11L1F84546 |
| 5. | SADHA2A11L1F84563 |
| 6. | SADHA2A11L1F84661 |
| 7. | SADHA2A12L1F85821 |
| 8. | SADHA2A13L1F84533 |
| 9. | SADHA2A13L1F87903 |
| 10. | SADHA2A13P1630140 |
| 11. | SADHA2A14K1F62376 |
| 12. | SADHA2A14L1F83259 |
| 13. | SADHA2A14L1F87831 |
| 14. | SADHA2A14N1622934 |
| 15. | SADHA2A15L1F84520 |
| 16. | SADHA2A15L1F84548 |
| 17. | SADHA2A15L1F87868 |
| 18. | SADHA2A15L1F87935 |
| 19. | SADHA2A15N1624689 |
| 20. | SADHA2A16L1600995 |
| 21. | SADHA2A16L1F83697 |

| | |
|-----|-------------------|
| 22. | SADHA2A17L1F88505 |
| 23. | SADHA2A19M1614147 |
| 24. | SADHA2A1XL1600532 |
| 25. | SADHA2A1XL1F84612 |
| 26. | SADHA2A1XL1F87901 |