

安全召回詳情

編號	10000414
製造商	BMW
車輛類別	私家車
型號	X 系 (E70)
代理商 (查詢電話)	31936688
主題	檢查，如有需要，更換真空管路/制動助力器
進度	進行中
受影響車輛的底盤號碼	見以下表列：(最後七位號碼)
缺陷簡述及忽略的可能後果	在制動真空泵內的機油有機會進入真空管路然後進入制動助力器，進入的機油有機會令制動助力器內的分隔膜損毀。在個別情況，分隔膜會出現裂隙而引致制動助力系統損壞。
修正行動	如有需要，更換真空管路/制動助力器
製造日期	05/2006-03/2010
回收行動開始日期	12/02/2013
估計回收行動的完成日期	31/08/2013

1	LC96142
2	LC96143
3	LC96145
4	LC96149
5	LC96295
6	LC96296
7	LC96306
8	LC96413
9	LC96580
10	LC96581
11	LC96584
12	LC96585
13	LC96592
14	LC96627
15	LC96628
16	LC96635
17	LC96637
18	LC96638
19	LC96639
20	LC96640
21	LC96641
22	LC96642

23	LC96644
24	LC96645
25	LC96646
26	LC96648
27	LC96649
28	LC96651
29	LC96654
30	LC96656
31	LC96657
32	LC96658
33	LC96659
34	LC96671
35	LC96674
36	LC96685
37	LC96750
38	LC96751
39	LC96752
40	LC96758
41	LC96759
42	LC96760
43	LC96761
44	LC96762

45	LC96763
46	LC96764
47	LC96765
48	LC96766
49	LC96767
50	LC96769
51	LC96771
52	LC96772
53	LC96773
54	LC96774
55	LC96777
56	LC96778
57	LC96779
58	LC96780
59	LC96781
60	LC96783
61	LC96784
62	LC96786
63	LC96787
64	LC96788
65	LC96789
66	LC96790
67	LC96792
68	LC96793
69	LC96795
70	LC96803
71	LC96805
72	LC96806
73	LC96807
74	LC96842
75	LC96940
76	LC96988
77	LC96991
78	LC97012
79	LC97013
80	LC97027
81	LC97028
82	LC97030
83	LC97032
84	LC97036

85	LC97037
86	LC97045
87	LC97051
88	LC97053
89	LC97059
90	LC97063
91	LC97064
92	LC97069
93	LC97074
94	LC97075
95	LC97192
96	LC97194
97	LC97220
98	LC97221
99	LC97223
100	LC97225
101	LC97226
102	LC97227
103	LC97275
104	LC97292
105	LC97293
106	LC97341
107	LC97376
108	LC97396
109	LC97400
110	LC97410
111	LC97413
112	LC97424
113	LC97427
114	LC97428
115	LC97429
116	LC97489
117	LC97547
118	LC97594
119	LC97595
120	LC97601
121	LC97623
122	LC97643
123	LC97645
124	LC97648

125	LC97651
126	LC97744
127	LC97745
128	LC97746
129	LC97754
130	LC97787
131	LC97793
132	LC97795
133	LC97859
134	LC97898
135	LC97904
136	LC97907
137	LC97924
138	LC97932
139	LC97934
140	LC97944
141	LC97949
142	LC97950
143	LC97953
144	LJ52013
145	LJ52019
146	LJ52021
147	LJ52023
148	LJ52024
149	LJ52025
150	LJ52026
151	LJ52146
152	LJ52148
153	LJ52346
154	LJ52367
155	LJ52519
156	LJ52520
157	LJ52523
158	LJ52527
159	LJ52529
160	LJ52576
161	LJ52581
162	LJ52589
163	LJ52636
164	LJ52651

165	LJ52731
166	LJ52892
167	LJ52909
168	LJ52944
169	LJ52945
170	LJ52952
171	LJ52953
172	LJ52954
173	LJ52955
174	LJ52956
175	LJ52957
176	LJ52958
177	LJ52959
178	LJ52960
179	LJ52961
180	LJ52963
181	LJ52965
182	LJ52973
183	LJ53003
184	LJ53005
185	LJ53011
186	LJ53014
187	LJ53015
188	LJ53024
189	LJ53042
190	LJ53049
191	LJ53053
192	LJ53096
193	LJ53128
194	LJ53152
195	LJ85015
196	LJ85017
197	LJ85018
198	LJ85083
199	LJ85085
200	LJ88025
201	LJ88026
202	LJ88027
203	LJ88029
204	LJ88069

205	LJ88070
206	LJ88071
207	LJ88074
208	LJ88159
209	LJ88199
210	LJ88363
211	LJ88392
212	LJ88464
213	LJ88479
214	LJ88491
215	LK28135
216	LK28287
217	LK28389
218	LK28397
219	LK28589
220	LK28614
221	LK28645