

安全召回詳情

| | |
|--------------|--|
| 編號 | 10000855 |
| 製造商 | 凌志 |
| 車輛類別 | 私家車 |
| 型號 | LS350/LS500/LS500h/IS300h |
| 代理商 (查詢電話) | 皇冠汽車有限公司(2880 4922) |
| 主題 | 更換防爆輪胎 |
| 進度 | 進行中 |
| 受影響車輛的底盤號碼 | 見以下表列: |
| 缺陷簡述及忽略的可能後果 | 召回之主要原因是與安裝輪胎過程不當有關，而引致輪胎有可能會發出異常聲響或震動的情況。 |
| 修正行動 | 更換輪胎 |
| 製造日期 | 2017 年 9 月至 2018 年 7 月 |
| 回收行動開始日期 | 2019 年 3 月 |
| 估計回收行動的完成日期 | 2020 年 12 月 |

| | |
|----|-------------------|
| 1 | JTHB4LFF005001399 |
| 2 | JTHB4LFF005001953 |
| 3 | JTHB4LFF005001967 |
| 4 | JTHB4LFF005002312 |
| 5 | JTHB4LFF105001489 |
| 6 | JTHB4LFF105001511 |
| 7 | JTHB4LFF105001671 |
| 8 | JTHB4LFF305002479 |
| 9 | JTHB4LFF305002577 |
| 10 | JTHB4LFF405001924 |
| 11 | JTHB4LFF505001446 |
| 12 | JTHB4LFF505001740 |
| 13 | JTHB4LFF505002337 |
| 14 | JTHB4LFF505002614 |
| 15 | JTHB4LFF505002645 |
| 16 | JTHB4LFF605002573 |
| 17 | JTHB4LFF705001058 |
| 18 | JTHB4LFF705001156 |
| 19 | JTHB4LFF805001599 |
| 20 | JTHB4LFF805002364 |
| 21 | JTHB4LFF805002428 |
| 22 | JTHB4LFF905001725 |
| 23 | JTHB4LFFX05001362 |
| 24 | JTHB4LFFX05001586 |
| 25 | JTHB5LFF005000556 |

| | |
|----|-------------------|
| 26 | JTHB5LFF005002999 |
| 27 | JTHB5LFF005003148 |
| 28 | JTHB5LFF005004901 |
| 29 | JTHB5LFF005005000 |
| 30 | JTHB5LFF105004292 |
| 31 | JTHB5LFF205003183 |
| 32 | JTHB5LFF205004401 |
| 33 | JTHB5LFF205005189 |
| 34 | JTHB5LFF305003080 |
| 35 | JTHB5LFF305003158 |
| 36 | JTHB5LFF305003788 |
| 37 | JTHB5LFF305004326 |
| 38 | JTHB5LFF405003959 |
| 39 | JTHB5LFF405004321 |
| 40 | JTHB5LFF505002383 |
| 41 | JTHB5LFF505003744 |
| 42 | JTHB5LFF505003906 |
| 43 | JTHB5LFF605002487 |
| 44 | JTHB5LFF605002554 |
| 45 | JTHB5LFF605002781 |
| 46 | JTHB5LFF605003882 |
| 47 | JTHB5LFF605003932 |
| 48 | JTHB5LFF605004336 |
| 49 | JTHB5LFF605004837 |
| 50 | JTHB5LFF705003972 |

| | |
|----|-------------------|
| 51 | JTHB5LFF705004393 |
| 52 | JTHB5LFF705004474 |
| 53 | JTHB5LFF905002466 |
| 54 | JTHB5LFF905005352 |
| 55 | JTHB5LFFX05002900 |
| 56 | JTHB5LFFX05002976 |
| 57 | JTHB5LFFX05003870 |
| 58 | JTHB5LFFX05004436 |
| 59 | JTHB5LFFX05004467 |
| 60 | JTHBH1D2005069940 |
| 61 | JTHBH1D2005070490 |
| 62 | JTHBH1D2105069980 |
| 63 | JTHBH1D2105072068 |
| 64 | JTHBH1D2105073415 |
| 65 | JTHBH1D2205067154 |
| 66 | JTHBH1D2205070667 |
| 67 | JTHBH1D2205070877 |
| 68 | JTHBH1D2205071995 |
| 69 | JTHBH1D2305066952 |
| 70 | JTHBH1D2305067194 |
| 71 | JTHBH1D2305070452 |
| 72 | JTHBH1D2405067043 |
| 73 | JTHBH1D2405069830 |
| 74 | JTHBH1D2405070752 |
| 75 | JTHBH1D2505072686 |
| 76 | JTHBH1D2505073028 |
| 77 | JTHBH1D2605066931 |
| 78 | JTHBH1D2605070557 |
| 79 | JTHBH1D2605070770 |
| 80 | JTHBH1D2805069765 |
| 81 | JTHBH1D2805070690 |
| 82 | JTHBH1D2905070178 |
| 83 | JTHBH1D2X05069797 |
| 84 | JTHBH1D2X05070111 |
| 85 | JTHBYLFF005000788 |
| 86 | JTHBYLFF005001665 |
| 87 | JTHBYLFF005002654 |
| 88 | JTHBYLFF105002324 |
| 89 | JTHBYLFF205002154 |
| 90 | JTHBYLFF205003028 |
| 91 | JTHBYLFF305000865 |

| | |
|-----|-------------------|
| 92 | JTHBYLFF305003233 |
| 93 | JTHBYLFF505001631 |
| 94 | JTHBYLFF505002066 |
| 95 | JTHBYLFF505002648 |
| 96 | JTHBYLFF505003203 |
| 97 | JTHBYLFF605000875 |
| 98 | JTHBYLFF705002439 |
| 99 | JTHBYLFF805000957 |
| 100 | JTHBYLFF905000773 |
| 101 | JTHBYLFF905000840 |
| 102 | JTHBYLFF905001647 |
| 103 | JTHBYLFF905002099 |
| 104 | JTHBYLFF905002572 |
| 105 | JTHBYLFFX05002600 |