

安全召回詳情

編號	10000893
製造商	日產
車輛類別	輕型貨車
型號	NV350 URVAN (E26)
代理商 (查詢電話)	合誠汽車有限公司 (Tel: 2216 8228)
主題	更換發電機及皮帶
進度	進行中
受影響車輛的底盤號碼	見以下表列:
缺陷簡述及忽略的可能後果	由於發電機單向離合器受阻使皮帶瞬間增加了張緊力，有機會導致轉向液壓泵固定托架因金屬疲勞而斷裂。 在少數的案例中，轉向動力輔助會降低，加重轉向力的力度。
修正行動	更換發電機及皮帶
製造日期	2013 至 2016 年
回收行動開始日期	2019 年 11 月 21 日
估計回收行動的完成日期	2029 年 11 月 21 日

NV350 URVAN (E26)

1	VR2E26-006750	54	VR2E26-032331	107	VR2E26-034900
2	VR2E26-009212	55	VR2E26-032440	108	VR2E26-034905
3	VR2E26-013925	56	VR2E26-033953	109	VR2E26-034912
4	VR2E26-015152	57	VR2E26-033982	110	VR2E26-034913
5	VR2E26-017057	58	VR2E26-033983	111	VR2E26-034914
6	VR2E26-025248	59	VR2E26-033985	112	VR2E26-034921
7	VR2E26-025352	60	VR2E26-034009	113	VR2E26-034925
8	VR2E26-026711	61	VR2E26-034022	114	VR2E26-034927
9	VR2E26-026718	62	VR2E26-034026	115	VR2E26-035221
10	VR2E26-026721	63	VR2E26-034033	116	VR2E26-035224
11	VR2E26-026725	64	VR2E26-034050	117	VR2E26-035225
12	VR2E26-026733	65	VR2E26-034065	118	VR2E26-035232
13	VR2E26-026736	66	VR2E26-034098	119	VR2E26-035236
14	VR2E26-026750	67	VR2E26-034107	120	VR2E26-035238
15	VR2E26-026755	68	VR2E26-034117	121	VR2E26-035251
16	VR2E26-026764	69	VR2E26-034118	122	VR2E26-035252
17	VR2E26-026765	70	VR2E26-034121	123	VR2E26-035255
18	VR2E26-026766	71	VR2E26-034132	124	VR2E26-035258
19	VR2E26-026768	72	VR2E26-034142	125	VR2E26-035265
20	VR2E26-026770	73	VR2E26-034143	126	VR2E26-035266
21	VR2E26-026778	74	VR2E26-034159	127	VR2E26-035276
22	VR2E26-026788	75	VR2E26-034169	128	VR2E26-035279
23	VR2E26-026789	76	VR2E26-034184	129	VR2E26-035281
24	VR2E26-026792	77	VR2E26-034194	130	VR2E26-035287
25	VR2E26-026795	78	VR2E26-034208	131	VR2E26-035290
26	VR2E26-026801	79	VR2E26-034216	132	VR2E26-035291
27	VR2E26-026806	80	VR2E26-034219	133	VR2E26-035300
28	VR2E26-026807	81	VR2E26-034797	134	VR2E26-035309
29	VR2E26-026809	82	VR2E26-034810	135	VR2E26-035323
30	VR2E26-026812	83	VR2E26-034811	136	VR2E26-035325
31	VR2E26-026818	84	VR2E26-034812	137	VR2E26-035330
32	VR2E26-026834	85	VR2E26-034813	138	VR2E26-035331
33	VR2E26-026835	86	VR2E26-034814	139	VR2E26-035794
34	VR2E26-026845	87	VR2E26-034821	140	VR2E26-035822
35	VR2E26-026850	88	VR2E26-034823	141	VR2E26-035823
36	VR2E26-026852	89	VR2E26-034826	142	VR2E26-035836
37	VR2E26-026861	90	VR2E26-034838	143	VR2E26-035870
38	VR2E26-026868	91	VR2E26-034839	144	VR2E26-035875
39	VR2E26-026869	92	VR2E26-034841	145	VR2E26-035879
40	VR2E26-026875	93	VR2E26-034844	146	VR2E26-035892

41	VR2E26-026881	94	VR2E26-034847	147	VR2E26-035900
42	VR2E26-026888	95	VR2E26-034857	148	VR2E26-035921
43	VR2E26-026889	96	VR2E26-034863	149	VR2E26-035945
44	VR2E26-026891	97	VR2E26-034865	150	VR2E26-035955
45	VR2E26-029205	98	VR2E26-034868	151	VR2E26-035956
46	VR2E26-029232	99	VR2E26-034870	152	VR2E26-035982
47	VR2E26-029252	100	VR2E26-034871	153	VR2E26-036011
48	VR2E26-029253	101	VR2E26-034874	154	VR2E26-036013
49	VR2E26-029265	102	VR2E26-034888	155	VR2E26-036036
50	VR2E26-029270	103	VR2E26-034890	156	VR2E26-036037
51	VR2E26-029290	104	VR2E26-034893	157	VR2E26-036046
52	VR2E26-029294	105	VR2E26-034897		
53	VR2E26-032200	106	VR2E26-034899		