

安全召回詳情

編號	10000895
製造商	富士
車輛類別	私家車
型號	SUBARU Legacy
代理商 (查詢電話)	意美九龍有限公司 (23936118)
主題	召回車輛更換儀錶內保險絲
進度	進行中
受影響車輛的底盤號碼	見以下列表
缺陷簡述及忽略的可能後果	是次召回行動所涉及的車輛，由於儀表板上的電路結構失常，如果長時間暴露在潮濕環境中，電路板內電線可能會導致短路，導致電路板過熱。對汽車的安全性增加一定風險。
修正行動	進行更換儀錶內保險絲部件
製造日期	1999-2001
回收行動開始日期	2019年04月4日
估計回收行動的完成日期	2021年12月31日

1	BE5-011779
2	BE5-011781
3	BE5-011785
4	BE5-011788
5	BE5-011797
6	BE5-011818
7	BE5-011823
8	BE5-011862
9	BE5-011872
10	BE5-011873
11	BE5-011889
12	BE5-011982
13	BE5-037638
14	BE5-037645
15	BE5-037657
16	BE5-037661
17	BE5-037696
18	BE5-037710
19	BE5-037712
20	BE5-037715
21	BH5-090581
22	BE5-063537
23	BE5-063626
24	BE5-063919

25	BE5-064105
26	BE5-064304
27	BE5-068260
28	BE5-068413
29	BE5-068426
30	BE5-068474
31	BE5-069309
32	BE5-069537
33	BE5-069545
34	BE5-069569
35	BE5-069626
36	BH5-114196
37	BH5-145602
38	BH5-145662
39	BE5-011776
40	BE5-011783
41	BE5-011786
42	BE5-011787
43	BE5-011789
44	BE5-011790
45	BE5-011795
46	BE5-011805
47	BE5-011842
48	BE5-011844

49	BE5-011864
50	BE5-011870
51	BE5-011876
52	BE5-011879
53	BE5-011880
54	BE5-011882
55	BE5-011886
56	BE5-011894
57	BE5-011895
58	BE5-011896
59	BE5-011905
60	BE5-011906
61	BE5-011915
62	BE5-011924
63	BE5-011929
64	BE5-011937
65	BE5-011960
66	BE5-011961
67	BE5-011979
68	BE5-011981
69	BE5-011984
70	BE5-011988
71	BE5-011990
72	BE5-037629
73	BE5-037634
74	BE5-037639
75	BE5-037640
76	BE5-037641
77	BE5-037649
78	BE5-037664
79	BE5-037673
80	BE5-037682
81	BE5-037689
82	BE5-037694
83	BE5-037703
84	BE5-037704
85	BE5-037705
86	BH5-090555
87	BH5-090591
88	BH5-090597

89	BH5-096147
90	BH5-096149
91	BH5-096173
92	BH5-096185
93	BE5-063487
94	BE5-063519
95	BE5-063660
96	BE5-063668
97	BE5-063769
98	BE5-063788
99	BE5-063915
100	BE5-064013
101	BE5-064123
102	BE5-064218
103	BE5-064229
104	BE5-064251
105	BE5-064302
106	BE5-068120
107	BE5-068152
108	BE5-068164
109	BE5-068345
110	BE5-068364
111	BE5-068411
112	BE5-068417
113	BE5-068493
114	BE5-068506
115	BE5-068562
116	BE5-069166
117	BE5-069184
118	BE5-069204
119	BE5-069263
120	BE5-069266
121	BE5-069293
122	BE5-069382
123	BE5-069434
124	BE5-069462
125	BE5-069519
126	BE5-069594
127	BE5-069602
128	BE5-080779

129	BE5-080826
130	BE5-080842
131	BE5-080901
132	BE5-080984
133	BE5-081014
134	BE5-081061
135	BE5-081703
136	BE5-081707
137	BE5-081711
138	BE5-081723
139	BH5-114178
140	BH5-114645
141	BH5-120806
142	BH5-120976
143	BH5-120996
144	BH5-121108
145	BH5-121277
146	BH5-145635
147	BH5-145789
148	BH5-121157
149	BE5-011775
150	BE5-011825
151	BE5-011885
152	BE5-037663
153	BE5-037667
154	BE5-037698
155	BH5-090551
156	BH5-096217
157	BE5-068302
158	BE5-068483
159	BE5-068565
160	BE5-069373
161	BE5-069444
162	BE5-069592
163	BE5-080791
164	BE5-080857
165	BH5-114037
166	BH5-120876
167	BH5-120891
168	BH5-120960

169	BH5-121307
170	BH5-145752
171	BE5-011772
172	BE5-063500
173	BE5-064237
174	BE5-068369
175	BE5-068535
176	BE5-081051
177	BH5-114423
178	BE5-011814
179	BE5-068174