

安全召回詳情

編號	10000916
製造商	豐田
車輛類別	私家車
型號	RAV4
代理商 (查詢電話)	皇冠汽車有限公司(2880 4988)
主題	更換駕駛座安全氣囊
進度	進行中
受影響車輛的底盤號碼	見以下表列:
缺陷簡述及忽略的可能後果	主要原因是根據安全氣囊生產商高田於 2019 年 11 月 26 日提交的《缺陷信息報告》(19E-080)，駕駛座安全氣囊有機會未能快速展開或破裂，或增加意外風險。雖然未能確認有關可能性，但基於安全考量決定召回。
修正行動	更換駕駛座安全氣囊
製造日期	1997 年 12 月至 1999 年 8 月
回收行動開始日期	2020 年 2 月
估計回收行動的完成日期	2021 年 12 月

1	JT171SC1000215265
2	JT172SC1100173116
3	JT172SC1100171287
4	JT171SC1000195891
5	JT172SC1100172702
6	JT171SC1000177388
7	JT171SC1000178954
8	JT171SC1000196103
9	JT171SC1000195023
10	JT172SC1100173233
11	JT172SC1107153085
12	JT171SC1000179185
13	JT172SC1100171996
14	JT172SC1100172502
15	JT172SC1100174645
16	JT172SC1100171911
17	JT171SC1000178486
18	JT172SC1107151877
19	JT172SC1100171719
20	JT172SC1100171941
21	JT172SC1100171758
22	JT171SC1000177222
23	JT172SC1100173104
24	JT171SC1000178680
25	JT172SC1107108369
26	JT172SC1100173069

27	JT171SC1000178647
28	JT171SC1000204784
29	JT172SC1100172372
30	JT171SC1000177301
31	JT172SC1100172975
32	JT172SC1107128776
33	JT171SC1000186082
34	JT172SC1100173164
35	JT172SC1100172764
36	JT171SC1000188981
37	JT171SC1000178467
38	JT171SC1000178534
39	JT171SC1000179533
40	JT171SC1000196005
41	JT171SC1000178734
42	JT171SC1000177511
43	JT171SC1000179373
44	JT171SC1000177353
45	JT172SC1100172895
46	JT172SC1100173176
47	JT172SC1100172932
48	JT171SC1000189026
49	JT171SC1000178960
50	JT171SC1000178626
51	JT171SC1000177157
52	JT171SC1000178810

53	JT171SC1000179229
54	JT171SC1000214793
55	JT172SC1100171432
56	JT172SC1107152780
57	JT171SC1000178041
58	JT171SC1000186481
59	JT172SC1100171013
60	JT172SC1100178172
61	JT171SC1000214886
62	JT171SC1000177751
63	JT172SC1100171299
64	JT172SC1100171474
65	JT172SC1100174260
66	JT171SC1000178580
67	JT171SC1000214580
68	JT172SC1107152133
69	JT171SC1000177664
70	JT171SC1000177847
71	JT171SC1000178392
72	JT171SC1000178759
73	JT171SC1000178798
74	JT171SC1000178863
75	JT171SC1000178905
76	JT171SC1000179009
77	JT171SC1000186447
78	JT171SC1000190559
79	JT171SC1000190661
80	JT171SC1000196173
81	JT172SC1100171624
82	JT172SC1100172126
83	JT172SC1100172383
84	JT172SC1100172826
85	JT172SC1100173034
86	JT172SC1107151595
87	JT172SC1107152261
88	JT172SC1107152901