

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda
型號 Model: CRV
項目 Subject: 更換點火器
Replace ignition switch

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

| | | | |
|----|-------------------|----|-------------------|
| 1 | JHLRD18400S000006 | 31 | JHLRD18400S000043 |
| 2 | JHLRD18400S000007 | 32 | JHLRD18400S000044 |
| 3 | JHLRD18400S000013 | 33 | JHLRD18400S000045 |
| 4 | JHLRD18400S000014 | 34 | JHLRD18400S000046 |
| 5 | JHLRD18400S000015 | 35 | JHLRD18400S000047 |
| 6 | JHLRD18400S000016 | 36 | JHLRD18400S000048 |
| 7 | JHLRD18400S000017 | 37 | JHLRD18400S000049 |
| 8 | JHLRD18400S000018 | 38 | JHLRD18400S000050 |
| 9 | JHLRD18400S000019 | 39 | JHLRD18400S000051 |
| 10 | JHLRD18400S000020 | 40 | JHLRD18400S000052 |
| 11 | JHLRD18400S000021 | 41 | JHLRD18400S000053 |
| 12 | JHLRD18400S000022 | 42 | JHLRD18400S000054 |
| 13 | JHLRD18400S000023 | 43 | JHLRD18400S000055 |
| 14 | JHLRD18400S000024 | 44 | JHLRD18400S000056 |
| 15 | JHLRD18400S000025 | 45 | JHLRD18400S000057 |
| 16 | JHLRD18400S000026 | 46 | JHLRD18400S000058 |
| 17 | JHLRD18400S000027 | 47 | JHLRD18400S000059 |
| 18 | JHLRD18400S000028 | 48 | JHLRD18400S000060 |
| 19 | JHLRD18400S000030 | 49 | JHLRD18400S000061 |
| 20 | JHLRD18400S000031 | 50 | JHLRD18400S000062 |
| 21 | JHLRD18400S000032 | 51 | JHLRD18400S000063 |
| 22 | JHLRD18400S000033 | 52 | JHLRD18400S000064 |
| 23 | JHLRD18400S000034 | 53 | JHLRD18400S000065 |
| 24 | JHLRD18400S000035 | 54 | JHLRD18400S000066 |
| 25 | JHLRD18400S000036 | 55 | JHLRD18400S000067 |
| 26 | JHLRD18400S000038 | 56 | JHLRD18400S000068 |
| 27 | JHLRD18400S000039 | 57 | JHLRD18400S000069 |
| 28 | JHLRD18400S000040 | 58 | JHLRD18400S000070 |
| 29 | JHLRD18400S000041 | 59 | JHLRD18400S000071 |
| 30 | JHLRD18400S000042 | 60 | JHLRD18400S000072 |

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda
型號 Model: CRV
項目 Subject: 更換點火器
Replace ignition switch

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

| | | | |
|----|-------------------|-----|-------------------|
| 61 | JHLRD18400S000073 | 91 | JHLRD18400S000106 |
| 62 | JHLRD18400S000074 | 92 | JHLRD18400S000107 |
| 63 | JHLRD18400S000075 | 93 | JHLRD18400S000108 |
| 64 | JHLRD18400S000076 | 94 | JHLRD18400S000110 |
| 65 | JHLRD18400S000077 | 95 | JHLRD18400S000111 |
| 66 | JHLRD18400S000078 | 96 | JHLRD18400S000113 |
| 67 | JHLRD18400S000081 | 97 | JHLRD18400S000114 |
| 68 | JHLRD18400S000082 | 98 | JHLRD18400S000115 |
| 69 | JHLRD18400S000083 | 99 | JHLRD18400S000116 |
| 70 | JHLRD18400S000084 | 100 | JHLRD18400S000117 |
| 71 | JHLRD18400S000085 | 101 | JHLRD18400S000118 |
| 72 | JHLRD18400S000086 | 102 | JHLRD18400S000119 |
| 73 | JHLRD18400S000087 | 103 | JHLRD18400S000120 |
| 74 | JHLRD18400S000088 | 104 | JHLRD18400S000122 |
| 75 | JHLRD18400S000089 | 105 | JHLRD18400S000123 |
| 76 | JHLRD18400S000090 | 106 | JHLRD18400S000124 |
| 77 | JHLRD18400S000091 | 107 | JHLRD18400S000125 |
| 78 | JHLRD18400S000092 | 108 | JHLRD18400S000126 |
| 79 | JHLRD18400S000093 | 109 | JHLRD18400S000127 |
| 80 | JHLRD18400S000094 | 110 | JHLRD18400S000128 |
| 81 | JHLRD18400S000095 | 111 | JHLRD18400S000129 |
| 82 | JHLRD18400S000096 | 112 | JHLRD18400S000130 |
| 83 | JHLRD18400S000097 | 113 | JHLRD18400S000131 |
| 84 | JHLRD18400S000098 | 114 | JHLRD18400S000132 |
| 85 | JHLRD18400S000100 | 115 | JHLRD18400S000255 |
| 86 | JHLRD18400S000101 | 116 | JHLRD18400S000256 |
| 87 | JHLRD18400S000102 | 117 | JHLRD18400S000355 |
| 88 | JHLRD18400S000103 | 118 | JHLRD18400S000356 |
| 89 | JHLRD18400S000104 | 119 | JHLRD18400S000357 |
| 90 | JHLRD18400S000105 | 120 | JHLRD18400S000358 |

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: CRV

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

| | | | |
|-----|-------------------|-----|-------------------|
| 121 | JHLRD18400S000359 | 151 | JHLRD18400S000479 |
| 122 | JHLRD18400S000360 | 152 | JHLRD18400S000480 |
| 123 | JHLRD18400S000361 | 153 | JHLRD18400S000481 |
| 124 | JHLRD18400S000362 | 154 | JHLRD18400S000482 |
| 125 | JHLRD18400S000363 | 155 | JHLRD18400S000483 |
| 126 | JHLRD18400S000364 | 156 | JHLRD18400S000484 |
| 127 | JHLRD18400S000365 | 157 | JHLRD18400S000485 |
| 128 | JHLRD18400S000366 | 158 | JHLRD18400S000486 |
| 129 | JHLRD18400S000367 | 159 | JHLRD18400S000487 |
| 130 | JHLRD18400S000368 | 160 | JHLRD18400S000488 |
| 131 | JHLRD18400S000415 | 161 | JHLRD18400S000489 |
| 132 | JHLRD18400S000416 | 162 | JHLRD18400S000542 |
| 133 | JHLRD18400S000418 | 163 | JHLRD18400S000543 |
| 134 | JHLRD18400S000420 | 164 | JHLRD18400S000544 |
| 135 | JHLRD18400S000421 | 165 | JHLRD18400S000545 |
| 136 | JHLRD18400S000422 | 166 | JHLRD18400S000546 |
| 137 | JHLRD18400S000423 | 167 | JHLRD18400S000547 |
| 138 | JHLRD18400S000424 | 168 | JHLRD18400S000548 |
| 139 | JHLRD18400S000425 | 169 | JHLRD18400S000549 |
| 140 | JHLRD18400S000426 | 170 | JHLRD18400S000550 |
| 141 | JHLRD18400S000427 | 171 | JHLRD18400S000551 |
| 142 | JHLRD18400S000428 | 172 | JHLRD18400S000552 |
| 143 | JHLRD18400S000429 | 173 | JHLRD18400S000553 |
| 144 | JHLRD18400S000430 | 174 | JHLRD18400S000554 |
| 145 | JHLRD18400S000431 | 175 | JHLRD18400S000555 |
| 146 | JHLRD18400S000432 | 176 | JHLRD18400S000556 |
| 147 | JHLRD18400S000433 | 177 | JHLRD18400S000557 |
| 148 | JHLRD18400S000434 | 178 | JHLRD18400S000558 |
| 149 | JHLRD18400S000476 | 179 | JHLRD18400S000559 |
| 150 | JHLRD18400S000478 | 180 | JHLRD18400S000560 |

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: CRV

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

| | | | |
|-----|-------------------|-----|-------------------|
| 181 | JHLRD18400S000561 | 211 | JHLRD18400S000940 |
| 182 | JHLRD18400S000562 | 212 | JHLRD18400S000942 |
| 183 | JHLRD18400S000563 | 213 | JHLRD18400S000943 |
| 184 | JHLRD18400S000564 | 214 | JHLRD18400S000944 |
| 185 | JHLRD18400S000565 | 215 | JHLRD18400S000945 |
| 186 | JHLRD18400S000566 | 216 | JHLRD18400S000946 |
| 187 | JHLRD18400S000567 | 217 | JHLRD18400S000947 |
| 188 | JHLRD18400S000568 | 218 | JHLRD18400S000948 |
| 189 | JHLRD18400S000569 | 219 | JHLRD18400S000949 |
| 190 | JHLRD18400S000570 | 220 | JHLRD18400S000950 |
| 191 | JHLRD18400S000571 | 221 | JHLRD18400S000951 |
| 192 | JHLRD18400S000572 | 222 | JHLRD18400S000952 |
| 193 | JHLRD18400S000573 | 223 | JHLRD18400S000953 |
| 194 | JHLRD18400S000574 | 224 | JHLRD18400S000954 |
| 195 | JHLRD18400S000575 | 225 | JHLRD18400S000955 |
| 196 | JHLRD18400S000576 | 226 | JHLRD18400S000956 |
| 197 | JHLRD18400S000577 | 227 | JHLRD18400S000957 |
| 198 | JHLRD18400S000578 | 228 | JHLRD18400S000958 |
| 199 | JHLRD18400S000579 | 229 | JHLRD18400S000959 |
| 200 | JHLRD18400S000580 | 230 | JHLRD18400S000960 |
| 201 | JHLRD18400S000581 | 231 | JHLRD18400S000961 |
| 202 | JHLRD18400S000582 | 232 | JHLRD18400S000962 |
| 203 | JHLRD18400S000583 | 233 | JHLRD18400S000963 |
| 204 | JHLRD18400S000584 | 234 | JHLRD18400S000964 |
| 205 | JHLRD18400S000585 | 235 | JHLRD18400S000965 |
| 206 | JHLRD18400S000931 | 236 | JHLRD18400S000967 |
| 207 | JHLRD18400S000932 | 237 | JHLRD18400S000968 |
| 208 | JHLRD18400S000933 | 238 | JHLRD18400S000971 |
| 209 | JHLRD18400S000934 | 239 | JHLRD18400S000972 |
| 210 | JHLRD18400S000936 | 240 | JHLRD18400S000973 |

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: CRV

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

| | | | |
|-----|-------------------|-----|-------------------|
| 241 | JHLRD18400S000975 | 271 | JHLRD18400S001012 |
| 242 | JHLRD18400S000976 | 272 | JHLRD18400S001013 |
| 243 | JHLRD18400S000978 | 273 | JHLRD18400S001014 |
| 244 | JHLRD18400S000980 | 274 | JHLRD18400S001015 |
| 245 | JHLRD18400S000981 | 275 | JHLRD18400S001016 |
| 246 | JHLRD18400S000982 | 276 | JHLRD18400S001017 |
| 247 | JHLRD18400S000983 | 277 | JHLRD18400S001018 |
| 248 | JHLRD18400S000984 | 278 | JHLRD18400S001019 |
| 249 | JHLRD18400S000985 | 279 | JHLRD18400S001020 |
| 250 | JHLRD18400S000986 | 280 | JHLRD18400S001081 |
| 251 | JHLRD18400S000987 | 281 | JHLRD18400S001082 |
| 252 | JHLRD18400S000988 | 282 | JHLRD18400S001083 |
| 253 | JHLRD18400S000989 | 283 | JHLRD18400S001084 |
| 254 | JHLRD18400S000990 | 284 | JHLRD18400S001085 |
| 255 | JHLRD18400S000991 | 285 | JHLRD18400S001086 |
| 256 | JHLRD18400S000993 | 286 | JHLRD18400S001087 |
| 257 | JHLRD18400S000995 | 287 | JHLRD18400S001088 |
| 258 | JHLRD18400S000996 | 288 | JHLRD18400S001089 |
| 259 | JHLRD18400S000997 | 289 | JHLRD18400S001090 |
| 260 | JHLRD18400S000998 | 290 | JHLRD18400S001091 |
| 261 | JHLRD18400S000999 | 291 | JHLRD18400S001092 |
| 262 | JHLRD18400S001000 | 292 | JHLRD18400S001093 |
| 263 | JHLRD18400S001001 | 293 | JHLRD18400S001094 |
| 264 | JHLRD18400S001003 | 294 | JHLRD18400S001095 |
| 265 | JHLRD18400S001004 | 295 | JHLRD18400S001096 |
| 266 | JHLRD18400S001005 | 296 | JHLRD18400S001097 |
| 267 | JHLRD18400S001006 | 297 | JHLRD18400S001368 |
| 268 | JHLRD18400S001007 | 298 | JHLRD18400S001369 |
| 269 | JHLRD18400S001008 | 299 | JHLRD18400S001370 |
| 270 | JHLRD18400S001009 | 300 | JHLRD18400S001371 |

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: CRV

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

| | |
|-----|-------------------|
| 301 | JHLRD18400S001372 |
| 302 | JHLRD18400S001373 |
| 303 | JHLRD18400S001374 |
| 304 | JHLRD18400S001375 |
| 305 | JHLRD18400S001376 |
| 306 | JHLRD18400S001377 |
| 307 | JHLRD18400S001378 |
| 308 | JHLRD18400S001379 |
| 309 | JHLRD18400S001380 |
| 310 | JHLRD18400S001381 |
| 311 | JHLRD18400S001382 |
| 312 | JHLRD18400S001383 |
| 313 | JHLRD18400S001384 |
| 314 | JHLRD18400S001385 |
| 315 | JHLRD18400S001386 |
| 316 | JHLRD18400S001387 |
| 317 | JHLRD18400S001464 |
| 318 | JHLRD18400S001564 |
| 319 | JHLRD18400S001565 |
| 320 | JHLRD18400S001567 |
| 321 | JHLRD18400S001568 |
| 322 | JHLRD18400S001570 |
| 323 | JHLRD18400S001571 |
| 324 | JHLRD18400S001572 |
| 325 | JHLRD18400S001575 |
| 326 | JHLRD18400S001576 |
| 327 | JHLRD18400S001577 |
| 328 | JHLRD18400S001578 |
| 329 | JHLRD18400S001579 |
| 330 | JHLRD18400S001581 |

| | |
|-----|-------------------|
| 331 | JHLRD18400S001585 |
| 332 | JHLRD18400S001587 |
| 333 | JHLRD18400S001590 |
| 334 | JHLRD18400S001591 |
| 335 | JHLRD18400S001593 |
| 336 | JHLRD18400S001594 |
| 337 | JHLRD18400S001595 |
| 338 | JHLRD18400S001596 |
| 339 | JHLRD18400S001599 |
| 340 | JHLRD18400S001600 |
| 341 | JHLRD18400S001601 |
| 342 | JHLRD18400S001628 |
| 343 | JHLRD18400S001629 |
| 344 | JHLRD18400S001630 |
| 345 | JHLRD18400S001632 |
| 346 | JHLRD18400S001633 |
| 347 | JHLRD18400S001634 |
| 348 | JHLRD18400S001635 |
| 349 | JHLRD18400S001636 |
| 350 | JHLRD18400S001637 |
| 351 | JHLRD18400S001741 |
| 352 | JHLRD18400S001742 |
| 353 | JHLRD18400S001743 |
| 354 | JHLRD18400S001745 |
| 355 | JHLRD18400S001746 |
| 356 | JHLRD18400S001747 |
| 357 | JHLRD18400S001749 |
| 358 | JHLRD18400S001750 |
| 359 | JHLRD18400S001751 |
| 360 | JHLRD18400S001752 |

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda

型號 Model: CRV

項目 Subject: 更換點火器

Replace ignition switch

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

| | | | |
|-----|-------------------|-----|-------------------|
| 361 | JHLRD18400S002038 | 391 | JHLRD18500C000319 |
| 362 | JHLRD18400S002039 | 392 | JHLRD18500C000320 |
| 363 | JHLRD18400S002040 | 393 | JHLRD18500C000321 |
| 364 | JHLRD18400S002041 | 394 | JHLRD18500C000322 |
| 365 | JHLRD18400S002042 | 395 | JHLRD18500C000323 |
| 366 | JHLRD18400S002043 | 396 | JHLRD18500C000650 |
| 367 | JHLRD18400S002044 | 397 | JHLRD18500C000651 |
| 368 | JHLRD18400S002045 | 398 | JHLRD18500C000652 |
| 369 | JHLRD18400S002046 | 399 | JHLRD18500C000653 |
| 370 | JHLRD18400S002047 | 400 | JHLRD18500C000654 |
| 371 | JHLRD18400S002048 | 401 | JHLRD18500C000655 |
| 372 | JHLRD18400S002049 | 402 | JHLRD18500C000656 |
| 373 | JHLRD18400S002050 | 403 | JHLRD18500C000657 |
| 374 | JHLRD18400S002051 | 404 | JHLRD18500C000658 |
| 375 | JHLRD18400S002052 | 405 | JHLRD18500C000659 |
| 376 | JHLRD18400S002053 | 406 | JHLRD18500C000660 |
| 377 | JHLRD18500C000210 | 407 | JHLRD18500C000661 |
| 378 | JHLRD18500C000211 | 408 | JHLRD18500C000662 |
| 379 | JHLRD18500C000212 | 409 | JHLRD18500C000663 |
| 380 | JHLRD18500C000213 | 410 | JHLRD18500C000664 |
| 381 | JHLRD18500C000214 | 411 | JHLRD18500C000665 |
| 382 | JHLRD18500C000215 | 412 | JHLRD18500C000666 |
| 383 | JHLRD18500C000310 | 413 | JHLRD18500C000667 |
| 384 | JHLRD18500C000311 | 414 | JHLRD18500C000668 |
| 385 | JHLRD18500C000312 | 415 | JHLRD18500C000669 |
| 386 | JHLRD18500C000313 | 416 | JHLRD18500C000670 |
| 387 | JHLRD18500C000314 | 417 | JHLRD18500C000671 |
| 388 | JHLRD18500C000316 | 418 | JHLRD18500C000672 |
| 389 | JHLRD18500C000317 | 419 | JHLRD18500C000860 |
| 390 | JHLRD18500C000318 | 420 | JHLRD18500C000861 |

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: 本田 Honda
型號 Model: CRV
項目 Subject: 更換點火器
Replace ignition switch

受影響車輛的車輛識別號碼

Involved Vehicle Identification Numbers

| | | | |
|-----|-------------------|-----|-------------------|
| 421 | JHLRD18500C000862 | 451 | JHLRD18500C001696 |
| 422 | JHLRD18500C000863 | 452 | JHLRD18500C001699 |
| 423 | JHLRD18500C000864 | 453 | JHLRD18500C001703 |
| 424 | JHLRD18500C000865 | 454 | JHLRD18500C001709 |
| 425 | JHLRD18500C000866 | 455 | JHLRD18500C001711 |
| 426 | JHLRD18500C001154 | 456 | JHLRD18500C001712 |
| 427 | JHLRD18500C001155 | 457 | JHLRD18500C001792 |
| 428 | JHLRD18500C001156 | 458 | JHLRD18500C001861 |
| 429 | JHLRD18500C001157 | 459 | JHLRD18500C001958 |
| 430 | JHLRD18500C001158 | 460 | JHLRD18500C001959 |
| 431 | JHLRD18500C001159 | 461 | JHLRD18500C001963 |
| 432 | JHLRD18500C001304 | 462 | JHLRD18500C001967 |
| 433 | JHLRD18500C001305 | 463 | JHLRD18500C001968 |
| 434 | JHLRD18500C001306 | 464 | JHLRD18500C001973 |
| 435 | JHLRD18500C001307 | 465 | JHLRD18500C001974 |
| 436 | JHLRD18500C001308 | 466 | JHLRD18500C001975 |
| 437 | JHLRD18500C001309 | 467 | JHLRD18500C001982 |
| 438 | JHLRD18500C001310 | 468 | JHLRD18500C001984 |
| 439 | JHLRD18500C001311 | 469 | JHLRD18500C001986 |
| 440 | JHLRD18500C001312 | 470 | JHLRD18500C001987 |
| 441 | JHLRD18500C001313 | 471 | JHLRD18500C001989 |
| 442 | JHLRD18500C001414 | 472 | JHLRD18500C002064 |
| 443 | JHLRD18500C001415 | 473 | JHLRD18500C002065 |
| 444 | JHLRD18500C001416 | | |
| 445 | JHLRD18500C001417 | | |
| 446 | JHLRD18500C001645 | | |
| 447 | JHLRD18500C001646 | | |
| 448 | JHLRD18500C001647 | | |
| 449 | JHLRD18500C001648 | | |
| 450 | JHLRD18500C001649 | | |