

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
1		JMYSREA2AVZ000584
2		JMYSREA2AVZ000880
3		JMYSREA2AWZ001740
4		JMYSREA2AXZ002060
5		jmysrea2axz003786
6		JMYSREA4AVZ000478
7		JMYSREA4AVZ000544
8		JMYSREA4AVZ001110
9		JMYSREA4AWZ000295
10		JMYSREA4AWZ000341
11		JMYSREA4AWZ000461
12		JMYSREA4AXZ000365
13		JMYSREA4AVZ000481
14		EA4A0000128
15		JMYSREA2AVZ001652
16		JMYSREA2AVZ003368
17		JMYSREA2AXZ003795
18		JMYSREA2AVZ001209
19		JMYSREA2AWZ004620
20		JMYSREA2AXZ002053
21		JMYSREA4AVZ000736
22		JMYSREA4AWZ000110
23	700	JMYSREA4AXZ000121
24		JMYSREA4AWZ000104
25	HE1820	EA4A0000112
26	LA1489	EA4A0000188
27	LE1250	EA4A0000189
28	HB126	EA4A0000212
29	HB1350	JMYSREA2AVZ000634
30	FR1198	JMYSREA2AVZ001262

	Reg Mark	Chassis Number
31	DF1976	JMYSREA2AVZ001273
32	HG1366	JMYSREA2AVZ002555
33	HL1216	JMYSREA2AVZ003099
34	HP1723	JMYSREA2AVZ003117
35	KU1054	JMYSREA2AWZ004540
36	EZ1180	JMYSREA2AWZ004667
37	AT1555	JMYSREA2AXZ001641
38	JL1469	JMYSREA2AXZ002048
39	JG1810	JMYSREA2AXZ002441
40	BC1251	JMYSREA2AXZ002671
41	LT1833	JMYSREA4AVZ000112
42	KT1864	JMYSREA4AVZ000191
43	HH1166	JMYSREA4AVZ000208
44	LD1507	JMYSREA4AVZ000223
45	JT1936	JMYSREA4AVZ000277
46	HD1640	JMYSREA4AVZ000351
47	LT1760	JMYSREA4AVZ000391
48	HD1179	JMYSREA4AVZ000476
49	HD1981	JMYSREA4AVZ000517
50	HD1940	JMYSREA4AVZ000528
51	FF1979	JMYSREA4AVZ000540
52	KW1083	JMYSREA4AVZ000562
53	GG1983	JMYSREA4AVZ000588
54	EZ1488	JMYSREA4AVZ000641
55	JM149	JMYSREA4AVZ000658
56	DW150	JMYSREA4AVZ000674
57	KM173	JMYSREA4AVZ000695
58	CU1603	JMYSREA4AVZ000708
59	EB1611	JMYSREA4AVZ000722
60	CZ1488	JMYSREA4AVZ000727

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
61	KL1789	JMYSREA4AVZ000741	91	JZ102	JMYSREA4AWZ000476
62	FR1909	JMYSREA4AVZ000903	92	GR1138	JMYSREA4AXZ000191
63	HF193	JMYSREA4AVZ000906	93	CM1229	JMYSREA4AXZ000232
64	HC1918	JMYSREA4AVZ000948	94	JK1032	JMYSREA4AXZ000361
65	KC1055	JMYSREA4AVZ000974	95	JP1450	JMYSREA4AXZ000417
66	KR1680	JMYSREA4AVZ000977	96	JT1739	JMYSREA4AXZ000454
67	HF1118	JMYSREA4AVZ000995	97	JT1678	JMYSREA7A1Z000119
68	LD1024	JMYSREA4AVZ001029	98	JU1788	JMYSREA7A1Z000121
69	LU1171	JMYSREA4AVZ001049	99	JB105	JMYSREA7A1Z000508
70	FM1892	JMYSREA4AVZ001086	100	JY1652	JMYSYEA3A1Z000101
71	JV117	JMYSREA4AVZ001134	101	FE156	JMYSREA4AVZ000254
72	CH1848	JMYSREA4AVZ001155	102	EB1877	JMYSREA4AVZ000259
73	LL1120	JMYSREA4AVZ001232	103	DK1193	JMYSREA4AVZ001163
74	JD1789	JMYSREA4AVZ001266	104	GG185	JMYSREA4AVZ001339
75	KU1147	JMYSREA4AVZ001321	105	JC1903	EA4A0000137
76	HJ1029	JMYSREA4AVZ001427	106	BL135	JMYSREA2AVZ000733
77		JMYSREA4AVZ001429	107	LD1541	JMYSREA2AVZ003046
78	LD1347	JMYSREA4AVZ001502	108	HV1371	JMYSREA2AWZ002943
79	FL1981	JMYSREA4AVZ001522	109	HD1372	JMYSREA4AVZ000474
80	JU1242	JMYSREA4AVZ001539	110	FJ1285	JMYSREA4AWZ000224
81	GB1684	JMYSREA4AVZ001694	111	GM1290	JMYSREA2AVZ000637
82	KV1722	JMYSREA4AVZ001711	112	KS1417	JMYSREA2AVZ001144
83	HN1866	JMYSREA4AVZ001724	113	HH1667	JMYSREA2AVZ002691
84	FK1996	JMYSREA4AVZ001730	114	HG1629	JMYSREA2AVZ002920
85	HR1439	JMYSREA4AVZ001738	115	EU1200	JMYSREA2AVZ002940
86	KA1884	JMYSREA4AWZ000116	116	JK1963	JMYSREA2AXZ003860
87	JN1860	JMYSREA4AWZ000193	117	JM1593	JMYSREA4AVZ000456
88	JR1817	JMYSREA4AWZ000285	118	HD1685	JMYSREA4AVZ000470
89	JB193	JMYSREA4AWZ000404	119	GK129	JMYSREA4AVZ000831
90	HX116	JMYSREA4AWZ000435	120	JE1722	JMYSREA4AVZ000947

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
121	HH1116	JMYSREA4AVZ001224
122	DF1955	JMYSREA4AVZ001411
123	HJ1907	JMYSREA4AVZ001438
124	LN1244	JMYSREA4AVZ001448
125	JT1841	JMYSREA4AVZ001509
126	HU1706	JMYSREA4AWZ000154
127	KY1266	JMYSREA4AWZ000232
128	LN1594	JMYSREA4AWZ000318
129	EC1157	JMYSREA4AWZ000463
130	JF1592	JMYSREA4AXZ000299
131	HS1314	JMYSREA4AXZ000472
132	KG1373	JMYSREA7A1Z000453
133	HN248	EA4A0000167
134	LL2387	EA4A0000184
135	LG2166	EA4A0000198
136	LP2741	JMYSREA2AVZ000642
137	HB2583	JMYSREA2AVZ000800
138	JH2154	JMYSREA2AVZ001111
139	FW2503	JMYSREA2AVZ001149
140	EN207	JMYSREA2AVZ001239
141	KS2948	JMYSREA2AVZ001257
142	KS2948	JMYSREA2AVZ001275
143	HD2795	JMYSREA2AVZ001341
144	EB246	JMYSREA2AVZ001391
145	EB271	JMYSREA2AVZ002650
146	HL2820	JMYSREA2AVZ003319
147	HP2835	JMYSREA2AWZ001639
148	HY2902	JMYSREA2AWZ004464
149	DP2611	JMYSREA2AXZ002421
150	JP2109	JMYSREA2AXZ003867

	Reg Mark	Chassis Number
151	JS2957	JMYSREA2AXZ004114
152	LD2904	JMYSREA4AVZ000168
153	LP2149	JMYSREA4AVZ000171
154	EE2208	JMYSREA4AVZ000175
155	JK2175	JMYSREA4AVZ000244
156	LU2134	JMYSREA4AVZ000267
157	HD2329	JMYSREA4AVZ000297
158	CW2188	JMYSREA4AVZ000299
159	JB2296	JMYSREA4AVZ000317
160	GF2938	JMYSREA4AVZ000328
161	HJ217	JMYSREA4AVZ000336
162	LJ2318	JMYSREA4AVZ000360
163	LE2023	JMYSREA4AVZ000483
164	LR2996	JMYSREA4AVZ000560
165	HD2761	JMYSREA4AVZ000616
166	LE2901	JMYSREA4AVZ000642
167	HE2793	JMYSREA4AVZ000643
168	HS2711	JMYSREA4AVZ000653
169	HE2923	JMYSREA4AVZ000681
170	GG2808	JMYSREA4AVZ000790
171	LB2496	JMYSREA4AVZ000811
172	HE293	JMYSREA4AVZ000850
173	JE2638	JMYSREA4AVZ000857
174	HX2700	JMYSREA4AVZ000890
175	GF256	JMYSREA4AVZ000937
176	BE2282	JMYSREA4AVZ000968
177	HF2639	JMYSREA4AVZ000986
178	BH2666	JMYSREA4AVZ000987
179	HF2053	JMYSREA4AVZ001006
180	HG2296	JMYSREA4AVZ001092

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
181	KX2806	JMYSREA4AVZ001176
182	FB2098	JMYSREA4AVZ001242
183	HH2631	JMYSREA4AVZ001292
184	HH2683	JMYSREA4AVZ001309
185	FJ2282	JMYSREA4AVZ001315
186	HH2901	JMYSREA4AVZ001316
187	HP270	JMYSREA4AVZ001370
188	HW2279	JMYSREA4AVZ001407
189	KS2680	JMYSREA4AVZ001433
190	LL204	JMYSREA4AVZ001456
191	HL2837	JMYSREA4AVZ001492
192	HL2629	JMYSREA4AVZ001504
193	LE250	JMYSREA4AVZ001553
194	JZ2119	JMYSREA4AVZ001590
195	GH2321	JMYSREA4AVZ001599
196	HM2859	JMYSREA4AVZ001614
197	HY266	JMYSREA4AVZ001622
198	GJ2475	JMYSREA4AVZ001628
199	LR2493	JMYSREA4AVZ001648
200	LP2675	JMYSREA4AVZ001670
201	LM223	JMYSREA4AVZ001686
202	DH281	JMYSREA4AVZ001729
203	GG2916	JMYSREA4AWZ000112
204	KF2889	JMYSREA4AWZ000166
205	FJ2147	JMYSREA4AWZ000182
206	HS2278	JMYSREA4AWZ000202
207	HU2957	JMYSREA4AWZ000291
208	HT2796	JMYSREA4AWZ000305
209	HW2548	JMYSREA4AWZ000342
210	KE208	JMYSREA4AWZ000362

	Reg Mark	Chassis Number
211	HW284	JMYSREA4AWZ000447
212	HR2988	JMYSREA4AWZ000606
213	JA2131	JMYSREA4AXZ000136
214	JC2843	JMYSREA4AXZ000197
215	HH2693	JMYSREA4AXZ000275
216	JF2892	JMYSREA4AXZ000289
217	JF2689	JMYSREA4AXZ000298
218	JK2364	JMYSREA4AXZ000355
219	HY2402	JMYSREA4AXZ000453
220	JJ2281	JMYSREA7A1Z000109
221	BT2866	JMYSREA7A1Z000456
222	HV2832	JMYSREA7A1Z000486
223	KS2526	JMYSREA7A2Z000195
224	HE2817	JMYSREA4AVZ000760
225	HF2248	JMYSREA4AVZ000959
226	HG2281	JMYSREA4AVZ001171
227	KT2524	JMYSREA4AWZ000307
228	FL2899	EA4A0000120
229	LH2216	EA4A0000199
230	HC2314	JMYSREA2AVZ001258
231	HH2695	JMYSREA2AVZ002759
232	HH2398	JMYSREA2AVZ003042
233	HL2698	JMYSREA2AVZ003104
234	HP2915	JMYSREA2AVZ003690
235	HP2576	JMYSREA4AVZ000104
236	DR218	JMYSREA4AVZ000147
237	HD2068	JMYSREA4AVZ000523
238	HE266	JMYSREA4AVZ000792
239	LN2805	JMYSREA4AVZ000966
240	HF2540	JMYSREA4AVZ001028

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
241	HF231	JMYSREA4AVZ001082	271	JP3059	JMYSREA4AVZ000305
242	FP2682	JMYSREA4AVZ001279	272	HD3111	JMYSREA4AVZ000372
243	HJ2317	JMYSREA4AVZ001382	273	JH3775	JMYSREA4AVZ000432
244	FR2666	JMYSREA4AVZ001525	274	FA3222	JMYSREA4AVZ000442
245	KM2909	JMYSREA4AVZ001534	275	KH3596	JMYSREA4AVZ000458
246	HL2656	JMYSREA4AVZ001576	276	HD3711	JMYSREA4AVZ000489
247	HR2433	JMYSREA4AVZ001601	277	HD3178	JMYSREA4AVZ000493
248	HX2219	JMYSREA4AWZ000296	278	KZ3167	JMYSREA4AVZ000494
249	HX2652	JMYSREA4AWZ000442	279	HD3603	JMYSREA4AVZ000521
250	JB2421	JMYSREA4AXZ000111	280	LL3341	JMYSREA4AVZ000680
251	HD3337	EA4A0000179	281	FE3567	JMYSREA4AVZ000739
252	LH3714	EA4A0000205	282	GX3332	JMYSREA4AVZ000757
253	GV3373	JMYSREA2AVZ000625	283	CL3221	JMYSREA4AVZ000768
254	KH3551	JMYSREA2AVZ000631	284	HP3389	JMYSREA4AVZ000772
255	HC3122	JMYSREA2AVZ001186	285	KU3325	JMYSREA4AVZ000784
256	CH317	JMYSREA2AVZ003089	286	JW3614	JMYSREA4AVZ000821
257	LB3273	JMYSREA2AWZ001689	287	GK390	JMYSREA4AVZ000837
258	DK3568	JMYSREA2AWZ004465	288	HE3979	JMYSREA4AVZ000872
259	HY3970	JMYSREA2AWZ004630	289	CV3989	JMYSREA4AVZ000897
260	JR3927	JMYSREA2AWZ004648	290	JT3395	JMYSREA4AVZ000913
261	HJ3301	JMYSREA2AXZ001543	291	JV3201	JMYSREA4AVZ000949
262	JR3100	JMYSREA2AXZ003853	292	HF311	JMYSREA4AVZ000960
263	HB3150	JMYSREA4AVZ000113	293	DV3132	JMYSREA4AVZ000961
264	HB3082	JMYSREA4AVZ000121	294	GA3778	JMYSREA4AVZ000964
265	HB3696	JMYSREA4AVZ000142	295	DM320	JMYSREA4AVZ000984
266	HB3342	JMYSREA4AVZ000146	296	HF3530	JMYSREA4AVZ001009
267	HB320	JMYSREA4AVZ000157	297	HF3310	JMYSREA4AVZ001032
268	FX3877	JMYSREA4AVZ000201	298	FH320	JMYSREA4AVZ001043
269	HC3570	JMYSREA4AVZ000231	299	HF3165	JMYSREA4AVZ001045
270	JU3893	JMYSREA4AVZ000241	300	ER3386	JMYSREA4AVZ001048

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number		Reg Mark	Chassis Number
301	EE3138	JMYSREA4AVZ001069	331	DR360	JMYSREA4AWZ000117
302	JR3328	JMYSREA4AVZ001105	332	HP3070	JMYSREA4AWZ000120
303	LD379	JMYSREA4AVZ001129	333	HP3385	JMYSREA4AWZ000129
304	DT348	JMYSREA4AVZ001130	334	HB315	JMYSREA4AWZ000145
305	HL3474	JMYSREA4AVZ001141	335	KX3327	JMYSREA4AWZ000165
306	LB3768	JMYSREA4AVZ001158	336	HP3971	JMYSREA4AWZ000169
307	LA3715	JMYSREA4AVZ001190	337	LA3114	JMYSREA4AWZ000174
308	JB3930	JMYSREA4AVZ001201	338	BW3313	JMYSREA4AWZ000181
309	DN308	JMYSREA4AVZ001210	339	GL3312	JMYSREA4AWZ000234
310	EW3285	JMYSREA4AVZ001234	340	JE3899	JMYSREA4AWZ000292
311	HJ3689	JMYSREA4AVZ001244	341	HV3648	JMYSREA4AWZ000316
312	LJ3398	JMYSREA4AVZ001272	342	HR3772	JMYSREA4AWZ000338
313	HH319	JMYSREA4AVZ001302	343	GG3765	JMYSREA4AWZ000395
314	HJ3900	JMYSREA4AVZ001391	344	JW3396	JMYSREA4AWZ000421
315	LK3449	JMYSREA4AVZ001435	345	EB3356	JMYSREA4AWZ000440
316	KB3843	JMYSREA4AVZ001447	346	LE3326	JMYSREA4AWZ000460
317	EG3622	JMYSREA4AVZ001457	347	JA3588	JMYSREA4AXZ000103
318	GU3287	JMYSREA4AVZ001482	348	JB3866	JMYSREA4AXZ000167
319	LN3506	JMYSREA4AVZ001489	349	GE385	JMYSREA4AXZ000296
320	HL3616	JMYSREA4AVZ001511	350	JL3731	JMYSREA4AXZ000371
321	KK3674	JMYSREA4AVZ001530	351	FM316	JMYSREA4AXZ000443
322	HL3758	JMYSREA4AVZ001549	352	CH339	JMYSREA4AXZ000452
323	HL3790	JMYSREA4AVZ001554	353	KG3670	JMYSREA7A2Z000112
324	HM3380	JMYSREA4AVZ001585	354	KJ3518	JMYSREA7A2Z000146
325	HR3380	JMYSREA4AVZ001587	355	HE3299	EA4A0000123
326	HM3673	JMYSREA4AVZ001610	356	KE3821	JMYSREA4AVZ000128
327	HM3866	JMYSREA4AVZ001620	357	EZ365	JMYSREA4AVZ000138
328	HM3938	JMYSREA4AVZ001638	358	HA3382	JMYSREA4AVZ000261
329	LT3217	JMYSREA4AVZ001664	359	HD3646	JMYSREA4AVZ000383
330	DY3892	JMYSREA4AVZ001739	360	HB337	JMYSREA4AVZ000495

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
361	CD3389	JMYSREA4AVZ000534
362	HD3343	JMYSREA4AVZ000576
363	FY3217	JMYSREA4AVZ000585
364	CS347	JMYSREA4AVZ000724
365	HF3476	JMYSREA4AVZ001075
366	KH3410	EA4A0000116
367	EX3611	EA4A0000158
368	KT3465	JMYSREA2AWZ001709
369	FB3635	JMYSREA4AVZ000158
370	LU3266	JMYSREA4AVZ001024
371	ED3163	JMYSREA4AVZ001112
372	FX3009	JMYSREA4AVZ001361
373	JA399	JMYSREA4AXZ000117
374	KC3490	JMYSREA7A1Z000510
375	KK3150	JMYSREA7A2Z000148
376	HC3087	JMYSREA2AVZ000821
377	GW3387	JMYSREA2AVZ001187
378	HM3675	JMYSREA2AVZ003330
379	JK3659	JMYSREA2AXZ001567
380	JK3319	JMYSREA2AXZ003862
381	HB3996	JMYSREA4AVZ000151
382	KB3188	JMYSREA4AVZ000210
383	GW3660	JMYSREA4AVZ000222
384	KX3478	JMYSREA4AVZ000429
385	HD3632	JMYSREA4AVZ000610
386	HE3403	JMYSREA4AVZ000849
387	ER3973	JMYSREA4AVZ001026
388	HJ3778	JMYSREA4AVZ001229
389	KD3110	JMYSREA4AVZ001263
390	KX3320	JMYSREA4AVZ001340

	Reg Mark	Chassis Number
391	HH3187	JMYSREA4AVZ001366
392	LA3365	JMYSREA4AVZ001408
393	HL3940	JMYSREA4AVZ001523
394	JC3994	JMYSREA4AVZ001712
395	LF3596	JMYSREA4AVZ001745
396	HP3989	JMYSREA4AWZ000152
397	HP3841	JMYSREA4AWZ000206
398	CS3281	JMYSREA4AXZ000101
399	HZ3310	JMYSREA4AXZ000102
400	LG3921	JMYSREA4AXZ000241
401	EE3007	JMYSREA4AXZ000389
402	JZ3222	JMYSREA4AXZ000459
403	KG3065	JMYSREA7A2Z000113
404	HE4307	EA4A0000113
405	EY4151	EA4A0000133
406	HA4978	JMYSREA2AVZ000619
407	JZ4107	JMYSREA2AVZ000784
408	JY4550	JMYSREA2AVZ001352
409	HG4962	JMYSREA2AVZ002446
410	HY4083	JMYSREA2AWZ004468
411	JF4198	JMYSREA2AXZ002409
412	LH4533	JMYSREA2AXZ002453
413	KT4760	JMYSREA2AXZ002491
414	JG4110	JMYSREA2AXZ002692
415	JN4832	JMYSREA2AXZ004075
416	FE4507	JMYSREA4AVZ000220
417	JE4482	JMYSREA4AVZ000229
418	LB403	JMYSREA4AVZ000245
419	LR4710	JMYSREA4AVZ000342
420	JN4398	JMYSREA4AVZ000371

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
421	HD4800	JMYSREA4AVZ000611
422	GD440	JMYSREA4AVZ000637
423	HV450	JMYSREA4AVZ000639
424	LS4620	JMYSREA4AVZ000649
425	HH4393	JMYSREA4AVZ000666
426	EC4898	JMYSREA4AVZ000718
427	HE403	JMYSREA4AVZ000734
428	JW4782	JMYSREA4AVZ000776
429	FR4111	JMYSREA4AVZ000912
430	LR4501	JMYSREA4AVZ000997
431	EJ4417	JMYSREA4AVZ001030
432	HG4661	JMYSREA4AVZ001187
433	LA4981	JMYSREA4AVZ001227
434	FN4862	JMYSREA4AVZ001280
435	FH4486	JMYSREA4AVZ001324
436	FU4919	JMYSREA4AVZ001330
437	BR4888	JMYSREA4AVZ001349
438	HJ4427	JMYSREA4AVZ001409
439	JD4522	JMYSREA4AVZ001462
440	KL4182	JMYSREA4AVZ001546
441	FJ498	JMYSREA4AVZ001642
442	JU4264	JMYSREA4AVZ001679
443	HM4822	JMYSREA4AVZ001695
444	HM4721	JMYSREA4AVZ001702
445	HM4632	JMYSREA4AVZ001728
446	FN4808	JMYSREA4AWZ000111
447	KC4401	JMYSREA4AWZ000238
448	KW426	JMYSREA4AWZ000306
449	KA499	JMYSREA4AWZ000326
450	LP4954	JMYSREA4AWZ000335

	Reg Mark	Chassis Number
451	KY4355	JMYSREA4AWZ000416
452	HY4801	JMYSREA4AWZ000417
453	GU4388	JMYSREA4AWZ000423
454	LB4532	JMYSREA4AWZ000467
455	LA4913	JMYSREA4AXZ000107
456	KJ4303	JMYSREA4AXZ000231
457	JW4340	JMYSREA7A1Z000143
458	KS4795	JMYSREA7A1Z000497
459	JS417	JMYSREA7A2Z000106
460	FJ405	JMYSREA4AVZ000186
461	HD4350	JMYSREA4AVZ000449
462	HD4415	JMYSREA4AVZ000579
463	HF4097	JMYSREA4AVZ001000
464	HJ4373	JMYSREA4AVZ001415
465	HM4295	JMYSREA4AVZ001639
466	LG4202	JMYSREA4AWZ000198
467	KD4544	EA4A0000208
468	HM4504	JMYSREA2AVZ003109
469	HB4564	JMYSREA4AVZ000144
470	KW4622	JMYSREA4AVZ000302
471	JJ453	JMYSREA4AVZ000526
472	LD4325	JMYSREA4AVZ000570
473	KN4521	JMYSREA4AVZ000874
474	FA4252	JMYSREA4AVZ001035
475	KX4865	JMYSREA4AVZ001081
476	LG4162	JMYSREA4AVZ001093
477	HU4481	JMYSREA4AVZ001160
478	KR4869	JMYSREA4AVZ001449
479	JR4420	JMYSREA4AVZ001469
480	KA4962	JMYSREA4AVZ001555

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
481	LE4568	JMYSREA4AVZ001726
482	FX408	JMYSREA4AWZ000103
483	HP4357	JMYSREA4AWZ000168
484	HV4229	JMYSREA4AWZ000425
485	GK4327	JMYSREA4AXZ000128
486	HZ4672	JMYSREA4AXZ000146
487	JV4188	JMYSREA4AXZ000281
488	CY432	JMYSREA4AXZ000415
489	HR5852	EA4A0000132
490	HB5509	JMYSREA2AVZ000682
491	KR5152	JMYSREA2AVZ000883
492	HF512	JMYSREA2AVZ001353
493	HJ5101	JMYSREA2AVZ001369
494	HP5559	JMYSREA2AWZ001539
495	HR5280	JMYSREA2AWZ001679
496	HA5902	JMYSREA2AWZ002950
497	KF517	JMYSREA2AWZ004651
498	FG529	JMYSREA2AXZ001587
499	JM5099	JMYSREA2AXZ003951
500	JR5116	JMYSREA2AXZ004099
501	JL5728	JMYSREA4AVZ000154
502	JV5813	JMYSREA4AVZ000156
503	KK5673	JMYSREA4AVZ000237
504	JD5703	JMYSREA4AVZ000251
505	LL5326	JMYSREA4AVZ000262
506	JD5091	JMYSREA4AVZ000279
507	HC5026	JMYSREA4AVZ000283
508	KY5498	JMYSREA4AVZ000331
509	KL5917	JMYSREA4AVZ000402
510	JH5403	JMYSREA4AVZ000424

	Reg Mark	Chassis Number
511	HD5730	JMYSREA4AVZ000426
512	KR5260	JMYSREA4AVZ000441
513	LP5255	JMYSREA4AVZ000484
514	LT5969	JMYSREA4AVZ000486
515	LV5898	JMYSREA4AVZ000554
516	KR5688	JMYSREA4AVZ000583
517	JT5472	JMYSREA4AVZ000584
518	LB542	JMYSREA4AVZ000589
519	HE5677	JMYSREA4AVZ000601
520	HJ5702	JMYSREA4AVZ000633
521	KV5769	JMYSREA4AVZ000678
522	KD5092	JMYSREA4AVZ000719
523	KJ5138	JMYSREA4AVZ000769
524	LK5315	JMYSREA4AVZ000820
525	JX5106	JMYSREA4AVZ000860
526	HZ5540	JMYSREA4AVZ000877
527	AS512	JMYSREA4AVZ000941
528	KH5233	JMYSREA4AVZ001005
529	LN5752	JMYSREA4AVZ001061
530	FD510	JMYSREA4AVZ001084
531	HV527	JMYSREA4AVZ001142
532	JZ5312	JMYSREA4AVZ001170
533	LA5713	JMYSREA4AVZ001173
534	HL5890	JMYSREA4AVZ001220
535	HG5991	JMYSREA4AVZ001243
536	KM5370	JMYSREA4AVZ001288
537	KS5052	JMYSREA4AVZ001300
538	HH5488	JMYSREA4AVZ001369
539	GZ5612	JMYSREA4AVZ001372
540	HJ5255	JMYSREA4AVZ001439

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
541	JJ5302	JMYSREA4AVZ001477
542	KY5127	JMYSREA4AVZ001491
543	JW5368	JMYSREA4AVZ001577
544	KJ5437	JMYSREA4AVZ001625
545	HM5796	JMYSREA4AVZ001663
546	KL5475	JMYSREA4AVZ001716
547	HN5288	JMYSREA4AWZ000114
548	HP5520	JMYSREA4AWZ000122
549	LR508	JMYSREA4AWZ000144
550	JC5941	JMYSREA4AWZ000146
551	KV5003	JMYSREA4AWZ000148
552	HP5556	JMYSREA4AWZ000157
553	HR5261	JMYSREA4AWZ000176
554	HS5241	JMYSREA4AWZ000233
555	CK5555	JMYSREA4AWZ000353
556	CC523	JMYSREA4AWZ000438
557	JA5700	JMYSREA4AWZ000456
558	JD5220	JMYSREA4AXZ000163
559	JB5510	JMYSREA4AXZ000226
560	JF5512	JMYSREA4AXZ000300
561	HA559	JMYSREA7A1Z000141
562	JZ5606	JMYSREA7A1Z000459
563	LE5390	JMYSREA7A1Z000493
564	HD5179	JMYSREA4AVZ000436
565	HD574	JMYSREA4AVZ000547
566	EV5188	JMYSREA4AVZ000581
567	HA5761	EA4A0000141
568	HA5145	JMYSREA2AVZ000641
569	HJ5679	JMYSREA2AVZ003095
570	HR5395	JMYSREA2AVZ003120

	Reg Mark	Chassis Number
571	HC5090	JMYSREA4AVZ000281
572	KN5214	JMYSREA4AVZ000296
573	CC523	JMYSREA4AVZ000438
574	FB5185	JMYSREA4AVZ000440
575	FN5970	JMYSREA4AVZ000705
576	HF5644	JMYSREA4AVZ001046
577	HJ5271	JMYSREA4AVZ001116
578	LR5063	JMYSREA4AVZ001458
579	KM5478	JMYSREA4AVZ001631
580	KM5261	JMYSREA4AVZ001649
581	JS5715	JMYSREA4AVZ001747
582	HP5183	JMYSREA4AWZ000135
583	JM5463	JMYSREA4AWZ000430
584	JA5805	JMYSREA4AXZ000115
585	BU5274	JMYSREA4AXZ000286
586	KU5932	JMYSREA7A2Z000205
587	KY6850	EA4A0000111
588	JC6766	EA4A0000121
589	HA6540	EA4A0000127
590	HA6409	EA4A0000138
591	HA6381	EA4A0000162
592	LE6013	JMYSREA2AVZ000614
593	LF6612	JMYSREA2AVZ000717
594	KW6630	JMYSREA2AVZ000934
595	DD602	JMYSREA2AVZ001143
596	HC6367	JMYSREA2AVZ001165
597	296	JMYSREA2AVZ001309
598	LM6438	JMYSREA2AVZ001315
599	HE6981	JMYSREA2AVZ001344
600	HH6117	JMYSREA2AVZ002875

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
601	HH6647	JMYSREA2AVZ002898
602	HS6020	JMYSREA2AWZ002847
603	DB6632	JMYSREA2AXZ001600
604	JC6018	JMYSREA2AXZ001610
605	JY6578	JMYSREA2AXZ001639
606	JF6880	JMYSREA2AXZ002031
607	DB6263	JMYSREA2AXZ003833
608	JM6272	JMYSREA2AXZ003938
609	KF6308	JMYSREA4AVZ000123
610	KM6370	JMYSREA4AVZ000141
611	JZ6923	JMYSREA4AVZ000149
612	JL6045	JMYSREA4AVZ000155
613	EK6269	JMYSREA4AVZ000172
614	JL6673	JMYSREA4AVZ000192
615	LJ6436	JMYSREA4AVZ000219
616	LB6800	JMYSREA4AVZ000225
617	FU6876	JMYSREA4AVZ000238
618	KE6663	JMYSREA4AVZ000248
619	BP699	JMYSREA4AVZ000271
620	HC6885	JMYSREA4AVZ000295
621	JT6366	JMYSREA4AVZ000310
622	HC6681	JMYSREA4AVZ000312
623	HC6656	JMYSREA4AVZ000321
624	JG6765	JMYSREA4AVZ000323
625	FV605	JMYSREA4AVZ000340
626	HH6377	JMYSREA4AVZ000366
627	EZ659	JMYSREA4AVZ000397
628	KF6330	JMYSREA4AVZ000407
629	HD648	JMYSREA4AVZ000416
630	HD6395	JMYSREA4AVZ000463

	Reg Mark	Chassis Number
631	FA6169	JMYSREA4AVZ000477
632	HD6398	JMYSREA4AVZ000480
633	KE6189	JMYSREA4AVZ000485
634	EG6018	JMYSREA4AVZ000502
635	HD6293	JMYSREA4AVZ000599
636	JM6248	JMYSREA4AVZ000600
637	DY6638	JMYSREA4AVZ000627
638	JA6346	JMYSREA4AVZ000677
639	LT6808	JMYSREA4AVZ000696
640	JU6874	JMYSREA4AVZ000712
641	HD6594	JMYSREA4AVZ000717
642	HD6962	JMYSREA4AVZ000747
643	HD6833	JMYSREA4AVZ000782
644	HE6021	JMYSREA4AVZ000858
645	JM6960	JMYSREA4AVZ000884
646	HP6445	JMYSREA4AVZ000893
647	LS693	JMYSREA4AVZ000957
648	HE6823	JMYSREA4AVZ000978
649	HF6299	JMYSREA4AVZ001014
650	HF6095	JMYSREA4AVZ001034
651	CW6678	JMYSREA4AVZ001090
652	KF632	JMYSREA4AVZ001102
653	HG6157	JMYSREA4AVZ001145
654	HG6595	JMYSREA4AVZ001178
655	JP6054	JMYSREA4AVZ001184
656	FF6128	JMYSREA4AVZ001193
657	JY6437	JMYSREA4AVZ001208
658	GC6988	JMYSREA4AVZ001260
659	FU6340	JMYSREA4AVZ001297
660	KW669	JMYSREA4AVZ001298

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
661	LG6248	JMYSREA4AVZ001306
662	LB6674	JMYSREA4AVZ001327
663	LF6904	JMYSREA4AVZ001367
664	FD6673	JMYSREA4AVZ001398
665	FH6899	JMYSREA4AVZ001418
666	HX6895	JMYSREA4AVZ001421
667	HJ6488	JMYSREA4AVZ001444
668	EE6636	JMYSREA4AVZ001536
669	KL6083	JMYSREA4AVZ001559
670	GU6883	JMYSREA4AVZ001567
671	KJ615	JMYSREA4AVZ001633
672	JV6562	JMYSREA4AVZ001657
673	HM6171	JMYSREA4AVZ001703
674	HM6242	JMYSREA4AVZ001737
675	KW6834	JMYSREA4AWZ000126
676	KB6387	JMYSREA4AWZ000127
677	FS6872	JMYSREA4AWZ000210
678	CN6318	JMYSREA4AWZ000229
679	HR6715	JMYSREA4AWZ000239
680	HS6058	JMYSREA4AWZ000258
681	HU622	JMYSREA4AWZ000269
682	EJ6998	JMYSREA4AWZ000273
683	HU6820	JMYSREA4AWZ000355
684	HT6829	JMYSREA4AWZ000413
685	HX6727	JMYSREA4AWZ000437
686	JA6807	JMYSREA4AWZ000480
687	CH663	JMYSREA4AWZ000481
688	JA6143	JMYSREA4AXZ000142
689	JW6715	JMYSREA4AXZ000159
690	JF6938	JMYSREA4AXZ000206

	Reg Mark	Chassis Number
691	GB6663	JMYSREA4AXZ000211
692	HG613	JMYSREA4AXZ000233
693	JP6889	JMYSREA4AXZ000287
694	JF6805	JMYSREA4AXZ000294
695	JL6095	JMYSREA4AXZ000372
696	JL6007	JMYSREA4AXZ000374
697	ES661	JMYSREA4AXZ000458
698	JX6740	JMYSREA7A1Z000132
699	GX6981	JMYSREA7A2Z000103
700	GW683	JMYSREA4AVZ000291
701	DD6661	JMYSREA4AVZ000425
702	JY6080	JMYSREA4AVZ000667
703	DU6881	JMYSREA4AVZ001104
704	HH6697	JMYSREA4AVZ001211
705	HH6049	JMYSREA4AVZ001257
706	HM6830	JMYSREA4AVZ001589
707	KZ605	JMYSREA4AVZ001466
708	EF6879	JMYSREA4AVZ001742
709	JF6698	JMYSREA4AXZ000444
710	HC6263	JMYSREA2AVZ000803
711	HB6806	JMYSREA2AVZ000811
712	HE6496	JMYSREA2AVZ001276
713	JV6697	JMYSREA2AVZ001330
714	DY6238	JMYSREA2AVZ002853
715	BW6898	JMYSREA2AVZ003092
716	JN6465	JMYSREA2AXZ003847
717	DH6860	JMYSREA4AVZ000140
718	DJ6833	JMYSREA4AVZ000247
719	JX6575	JMYSREA4AVZ000255
720	KK6047	JMYSREA4AVZ000268

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
721	EJ6998*	JMYSREA4AVZ000273
722	JP609	JMYSREA4AVZ000349
723	LA6662	JMYSREA4AVZ000364
724	KW6626	JMYSREA4AVZ000503
725	KN6375	JMYSREA4AVZ000609
726	HB6003	JMYSREA4AVZ000654
727	HD6711	JMYSREA4AVZ000726
728	HE6101	JMYSREA4AVZ000796
729	HD6631	JMYSREA4AVZ000805
730	JA6732	JMYSREA4AVZ000806
731	JH6392	JMYSREA4AVZ000902
732	JS6897	JMYSREA4AVZ000909
733	JG601	JMYSREA4AVZ001202
734	HJ6985	JMYSREA4AVZ001467
735	HM6814	JMYSREA4AVZ001725
736	HX6797	JMYSREA4AWZ000369
737	JK6613	JMYSREA4AXZ000358
738	JX6702	JMYSREA4AXZ000471
739	KR6683	JMYSREA7A2Z000190
740	HW7072	EA4A0000165
741	HA7456	EA4A0000171
742	HA7357	JMYSREA2AVZ000640
743	HL7720	JMYSREA2AVZ003103
744	LL7083	JMYSREA2AVZ003306
745	HM7648	JMYSREA2AVZ003565
746	HT7085	JMYSREA2AWZ001697
747	HT7329	JMYSREA2AWZ002848
748	GH7808	JMYSREA2AXZ001555
749	JE7476	JMYSREA2AXZ001932
750	HZ7996	JMYSREA2AXZ002061

	Reg Mark	Chassis Number
751	JD7148	JMYSREA2AXZ002437
752	GK7822	JMYSREA2AXZ003850
753	HN7969	JMYSREA4AVZ000196
754	KG7145	JMYSREA4AVZ000209
755	LP7402	JMYSREA4AVZ000376
756	HC7757	JMYSREA4AVZ000423
757	HC7673	JMYSREA4AVZ000435
758	KC7871	JMYSREA4AVZ000490
759	KF7283	JMYSREA4AVZ000513
760	HD7131	JMYSREA4AVZ000565
761	LR7257	JMYSREA4AVZ000688
762	HD7849	JMYSREA4AVZ000698
763	HD7513	JMYSREA4AVZ000752
764	HD7045	JMYSREA4AVZ000754
765	CV734	JMYSREA4AVZ000773
766	CU729	JMYSREA4AVZ000793
767	LH7904	JMYSREA4AVZ000800
768	KR7746	JMYSREA4AVZ000814
769	FN753	JMYSREA4AVZ000827
770	LM7084	JMYSREA4AVZ000917
771	HE7186	JMYSREA4AVZ000921
772	HE7392	JMYSREA4AVZ000950
773	HE7838	JMYSREA4AVZ000965
774	HE7256	JMYSREA4AVZ000973
775	KB7767	JMYSREA4AVZ000990
776	JJ7157	JMYSREA4AVZ001055
777	JW7577	JMYSREA4AVZ001115
778	HB7739	JMYSREA4AVZ001126
779	KX7845	JMYSREA4AVZ001139
780	DS736	JMYSREA4AVZ001209

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
781	KZ7760	JMYSREA4AVZ001218
782	LR7608	JMYSREA4AVZ001219
783	KE7339	JMYSREA4AVZ001230
784	JT7522	JMYSREA4AVZ001299
785	LD7217	JMYSREA4AVZ001413
786	JM774	JMYSREA4AVZ001422
787	KG7966	JMYSREA4AVZ001495
788	KS768	JMYSREA4AVZ001540
789	EL7022	JMYSREA4AVZ001584
790	FZ7111	JMYSREA4AVZ001591
791	LL7448	JMYSREA4AVZ001612
792	LG7161	JMYSREA4AVZ001646
793	HM7003	JMYSREA4AVZ001661
794	HM7951	JMYSREA4AVZ001683
795	HM7608	JMYSREA4AVZ001709
796	HM7429	JMYSREA4AVZ001723
797	LK7384	JMYSREA4AWZ000208
798	HL710	JMYSREA4AWZ000248
799	HT721	JMYSREA4AWZ000252
800	DZ782	JMYSREA4AWZ000351
801	HT7906	JMYSREA4AWZ000400
802	JE713	JMYSREA4AWZ000424
803	KT768	JMYSREA4AWZ000471
804	JA7819	JMYSREA4AWZ000485
805	JT7890	JMYSREA4AXZ000124
806	JU730	JMYSREA4AXZ000126
807	EZ7773	JMYSREA4AXZ000129
808	FZ7773	JMYSREA4AXZ000359
809	HD7042	JMYSREA4AXZ000360
810	JM7976	JMYSREA4AXZ000428

	Reg Mark	Chassis Number
811	JS7736	JMYSREA4AXZ000445
812	JT7866	JMYSREA7A1Z000110
813	LF7188	JMYSREA7A1Z000111
814	JU7922	JMYSREA7A1Z000115
815	JT7890	JMYSREA7A1Z000124
816	JU7397	JMYSREA7A1Z000142
817	HC7096	JMYSREA4AVZ000377
818	HD7469	JMYSREA4AVZ000618
819	HF7430	JMYSREA4AVZ001095
820	HH7859	JMYSREA4AVZ001225
821	HH7719*	JMYSREA4AVZ001271
822	HP7315	JMYSREA4AWZ000186
823	HT7333	JMYSREA2AWZ002484
824	KB7012	EA4A0000151
825	KW7863	JMYSREA2AXZ001649
826	LJ7538	JMYSREA2AXZ003775
827	LR7307	JMYSREA4AVZ000207
828	KT7860	JMYSREA4AVZ000224
829	JU7415	JMYSREA4AVZ000625
830	HD7142	JMYSREA4AVZ000661
831	CA736	JMYSREA4AVZ000668
832	KW7756	JMYSREA4AVZ000692
833	HD7009	JMYSREA4AVZ000775
834	EH712	JMYSREA4AVZ000804
835	BM7783	JMYSREA4AVZ000807
836	KV7457	JMYSREA4AVZ000840
837	KE7665	JMYSREA4AVZ000891
838	KF7400	JMYSREA4AVZ000953
839	FD7812	JMYSREA4AVZ000994
840	HF7955	JMYSREA4AVZ001039

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
841	JN7282	JMYSREA4AVZ001428
842	KG7280	JMYSREA4AVZ001734
843	HR7119	JMYSREA4AWZ000138
844	HR7192	JMYSREA4AWZ000170
845	HS7467	JMYSREA4AWZ000286
846	LB7558	JMYSREA4AWZ000298
847	JF7189	JMYSREA4AXZ000240
848	EH733	JMYSREA4AXZ000418
849	JU730	JMYSREA7A1Z000126
850	KU7949	JMYSREA7A2Z000198
851	DW8216	EA4A0000142
852	HT8033	EA4A0000144
853	CN8687	EA4A0000172
854	LD8308	EA4A0000200
855	CX829	EA4A0000207
856	HB8973	JMYSREA2AVZ000644
857	HC851	JMYSREA2AVZ000868
858	HB8878	JMYSREA2AVZ000950
859	HC8779	JMYSREA2AVZ001183
860	KU8497	JMYSREA2AVZ001208
861	KC8005	JMYSREA2AVZ001236
862	EU897	JMYSREA2AVZ001382
863	HF8299	JMYSREA2AVZ002606
864	FY8381	JMYSREA2AVZ003118
865	HT8352	JMYSREA2AWZ001737
866	JX8204	JMYSREA2AWZ002862
867	DR8889	JMYSREA2AWZ003134
868	EU8901	JMYSREA2AXZ001571
869	EG830	JMYSREA2AXZ001621
870	JA8938	JMYSREA4AVZ000108

	Reg Mark	Chassis Number
871	JV8638	JMYSREA4AVZ000148
872	KP8582	JMYSREA4AVZ000152
873	LA8408	JMYSREA4AVZ000183
874	KW8663	JMYSREA4AVZ000188
875	HR850	JMYSREA4AVZ000205
876	JB8435	JMYSREA4AVZ000213
877	KR8708	JMYSREA4AVZ000221
878	CC8827	JMYSREA4AVZ000236
879	JR8639	JMYSREA4AVZ000260
880	HC8445	JMYSREA4AVZ000266
881	DT8810	JMYSREA4AVZ000290
882	HC8457	JMYSREA4AVZ000301
883	JL8813	JMYSREA4AVZ000311
884	LG8132	JMYSREA4AVZ000322
885	KB8102	JMYSREA4AVZ000326
886	LR8083	JMYSREA4AVZ000358
887	HS8242	JMYSREA4AVZ000405
888	HC8005	JMYSREA4AVZ000418
889	HC8831	JMYSREA4AVZ000419
890	GZ860	JMYSREA4AVZ000431
891	HC8069	JMYSREA4AVZ000439
892	GX859	JMYSREA4AVZ000451
893	LR8699	JMYSREA4AVZ000491
894	JU8804	JMYSREA4AVZ000519
895	LL8533	JMYSREA4AVZ000553
896	HA884	JMYSREA4AVZ000556
897	HE8248	JMYSREA4AVZ000568
898	HD8481	JMYSREA4AVZ000594
899	EE8609	JMYSREA4AVZ000615
900	JT8809	JMYSREA4AVZ000619

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
901	AR812	JMYSREA4AVZ000651
902	GZ8889	JMYSREA4AVZ000671
903	LD8344	JMYSREA4AVZ000672
904	LA8248	JMYSREA4AVZ000704
905	HD8923	JMYSREA4AVZ000707
906	JZ8374	JMYSREA4AVZ000715
907	HB8926	JMYSREA4AVZ000738
908	HD8063	JMYSREA4AVZ000743
909	HD8793	JMYSREA4AVZ000749
910	HD8081	JMYSREA4AVZ000751
911	AY8766	JMYSREA4AVZ000755
912	KK8781	JMYSREA4AVZ000758
913	HD8751	JMYSREA4AVZ000777
914	HD8731	JMYSREA4AVZ000795
915	HE8892	JMYSREA4AVZ000803
916	LN8980	JMYSREA4AVZ000832
917	JS8003	JMYSREA4AVZ000839
918	HD834	JMYSREA4AVZ000846
919	LR8316	JMYSREA4AVZ000861
920	JJ8658	JMYSREA4AVZ000867
921	KU8346	JMYSREA4AVZ000894
922	KJ8450	JMYSREA4AVZ000969
923	GW8588	JMYSREA4AVZ001023
924	HC8236	JMYSREA4AVZ001071
925	LA8737	JMYSREA4AVZ001117
926	AA880	JMYSREA4AVZ001119
927	KH8702	JMYSREA4AVZ001137
928	JY840	JMYSREA4AVZ001165
929	LK8554	JMYSREA4AVZ001181
930	KH8625	JMYSREA4AVZ001197

	Reg Mark	Chassis Number
931	JU8205	JMYSREA4AVZ001198
932	HG8921	JMYSREA4AVZ001206
933	LF8904	JMYSREA4AVZ001215
934	EY8308	JMYSREA4AVZ001217
935	HG8417	JMYSREA4AVZ001252
936	LG8415	JMYSREA4AVZ001314
937	HD8882	JMYSREA4AVZ001329
938	HG8655	JMYSREA4AVZ001350
939	LB8111	JMYSREA4AVZ001362
940	HZ8057	JMYSREA4AVZ001365
941	FA819	JMYSREA4AVZ001401
942	HJ8198	JMYSREA4AVZ001441
943	EY884	JMYSREA4AVZ001503
944	HM8059	JMYSREA4AVZ001656
945	LG8516	JMYSREA4AVZ001671
946	GN8065	JMYSREA4AVZ001674
947	HM8987	JMYSREA4AVZ001714
948	LM8364	JMYSREA4AWZ000123
949	HP8500	JMYSREA4AWZ000140
950	HP8707	JMYSREA4AWZ000173
951	KZ8033	JMYSREA4AWZ000180
952	FA8216	JMYSREA4AWZ000201
953	KF8505	JMYSREA4AWZ000207
954	BS8862	JMYSREA4AWZ000242
955	LH8895	JMYSREA4AWZ000266
956	KX8434	JMYSREA4AWZ000278
957	KB8221	JMYSREA4AWZ000300
958	KX8858	JMYSREA4AWZ000308
959	HF8982	JMYSREA4AWZ000328
960	HV8103	JMYSREA4AWZ000331

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
961	HG8698	JMYSREA4AWZ000378
962	HV8949	JMYSREA4AWZ000385
963	EB8307	JMYSREA4AWZ000390
964	FS8925	JMYSREA4AWZ000410
965	HX8370	JMYSREA4AWZ000414
966	HV8696	JMYSREA4AWZ000418
967	HX836	JMYSREA4AWZ000446
968	LE835	JMYSREA4AWZ000468
969	JA864	JMYSREA4AXZ000122
970	JA8412	JMYSREA4AXZ000165
971	JF8553	JMYSREA4AXZ000236
972	JX830	JMYSREA4AXZ000354
973	JC809	JMYSREA4AXZ000467
974	CV8229	JMYSREA4AXZ000469
975	JZ8441	JMYSREA4AXZ000479
976	JY8103	JMYSREA7A1Z000112
977	KB8305	JMYSREA7A1Z000482
978	HA8267	JMYSREA7A1Z000504
979	KC8582	JMYSREA7A1Z000910
980	HC8494	JMYSREA4AVZ000385
981	he8081	JMYSREA4AVZ000693
982	HE8795	JMYSREA4AVZ000889
983	GS834	JMYSREA4AVZ000982
984	HJ8662	JMYSREA4AVZ001388
985	HJ8204	JMYSREA4AVZ001484
986	FA8466	JMYSREA2AVZ002827
987	KD8199	JMYSREA4AVZ000341
988	LU8708	JMYSREA4AVZ000452
989	KL8486	JMYSREA4AVZ001412
990	DY8388	JMYSREA4AWZ000124

	Reg Mark	Chassis Number
991	EU8422	EA4A0000149
992	HE8012	JMYSREA2AVZ001172
993	HJ8935	JMYSREA2AVZ001409
994	JD8062	JMYSREA2AXZ001646
995	JF8090	JMYSREA2AXZ002058
996	HF8522	JMYSREA2AXZ002467
997	JK8393	JMYSREA2AXZ003887
998	KW8801	JMYSREA4AVZ000228
999	HB803	JMYSREA4AVZ000308
1000	BB8688	JMYSREA4AVZ000447
1001	HD8440	JMYSREA4AVZ000647
1002	JW8862	JMYSREA4AVZ000659
1003	HD8169	JMYSREA4AVZ000770
1004	HE8861	JMYSREA4AVZ000910
1005	DK8682	JMYSREA4AVZ000962
1006	LT8648	JMYSREA4AVZ001013
1007	KX8909	JMYSREA4AVZ001025
1008	BX8892	JMYSREA4AVZ001056
1009	LA8846	JMYSREA4AVZ001058
1010	HF8910	JMYSREA4AVZ001077
1011	EZ8832	JMYSREA4AVZ001136
1012	FK8343	JMYSREA4AVZ001186
1013	KV8216	JMYSREA4AVZ001287
1014	FS805	JMYSREA4AVZ001572
1015	HM8209	JMYSREA4AVZ001693
1016	DM8810	JMYSREA4AWZ000150
1017	EA8666	JMYSREA4AWZ000329
1018	HR8813	JMYSREA4AWZ000344
1019	EM8018	JMYSREA4AWZ000452
1020	HU8315	JMYSREA4AWZ000479

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
1021	JD8941	JMYSREA4AXZ000133
1022	JJ8918	JMYSREA4AXZ000366
1023	LJ8767	JMYSREA4AXZ000468
1024	LF9746	EA4A0000118
1025	HZ9975	EA4A0000126
1026	HB995	JMYSREA2AVZ000626
1027	FW9700	JMYSREA2AVZ000633
1028	KG9690	JMYSREA2AVZ000787
1029	FN9950	JMYSREA2AVZ000849
1030	HG9001	JMYSREA2AVZ003054
1031	JH916	JMYSREA2AVZ003066
1032	HJ9549	JMYSREA2AVZ003072
1033	HV9253	JMYSREA2AWZ003238
1034	HV915	JMYSREA2AWZ004555
1035	KT9443	JMYSREA4AVZ000133
1036	HB9798	JMYSREA4AVZ000164
1037	HB9326	JMYSREA4AVZ000178
1038	LJ9451	JMYSREA4AVZ000190
1039	KR906	JMYSREA4AVZ000195
1040	HB9883	JMYSREA4AVZ000230
1041	FX9605	JMYSREA4AVZ000234
1042	HU9398	JMYSREA4AVZ000293
1043	FH9938	JMYSREA4AVZ000348
1044	DG9092	JMYSREA4AVZ000381
1045	JN9711	JMYSREA4AVZ000395
1046	HD917	JMYSREA4AVZ000453
1047	HD9190	JMYSREA4AVZ000462
1048	JG915	JMYSREA4AVZ000469
1049	EL9278	JMYSREA4AVZ000473
1050	JK9031	JMYSREA4AVZ000475

	Reg Mark	Chassis Number
1051	JV9048	JMYSREA4AVZ000496
1052	KL9975	JMYSREA4AVZ000591
1053]W9084	JMYSREA4AVZ000624
1054	HD9893	JMYSREA4AVZ000630
1055	JF933	JMYSREA4AVZ000657
1056	BT938	JMYSREA4AVZ000686
1057	FT9886	JMYSREA4AVZ000687
1058	HE9533	JMYSREA4AVZ000694
1059	AG906	JMYSREA4AVZ000750
1060	HD9322	JMYSREA4AVZ000787
1061	LE9118	JMYSREA4AVZ000816
1062	JC9935	JMYSREA4AVZ000852
1063	JH9045	JMYSREA4AVZ000868
1064	LA9247	JMYSREA4AVZ000876
1065	JF9516	JMYSREA4AVZ000881
1066	HE9939	JMYSREA4AVZ000888
1067	HE9020	JMYSREA4AVZ000930
1068	HE9143	JMYSREA4AVZ000946
1069	HE9577	JMYSREA4AVZ000958
1070	HE9921	JMYSREA4AVZ000976
1071	KM9133	JMYSREA4AVZ001040
1072	KB9063	JMYSREA4AVZ001051
1073	FF9030	JMYSREA4AVZ001070
1074	HF9865	JMYSREA4AVZ001079
1075	HF9135	JMYSREA4AVZ001111
1076	GE9763	JMYSREA4AVZ001114
1077	HF9012	JMYSREA4AVZ001133
1078	HG9860	JMYSREA4AVZ001259
1079	LN9660	JMYSREA4AVZ001274
1080	HG9346	JMYSREA4AVZ001290

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
1081	HG9666	JMYSREA4AVZ001295
1082	HG9060	JMYSREA4AVZ001336
1083	HG9388	JMYSREA4AVZ001347
1084	JL9930	JMYSREA4AVZ001383
1085	DM9693	JMYSREA4AVZ001414
1086	LM9279	JMYSREA4AVZ001632
1087	GT9808	JMYSREA4AVZ001669
1088	HL971	JMYSREA4AVZ001685
1089	KK9698	JMYSREA4AVZ001699
1090	HM9398	JMYSREA4AVZ001721
1091	LA9330	JMYSREA4AVZ001732
1092	EN9950	JMYSREA4AWZ000121
1093	GS9918	JMYSREA4AWZ000183
1094	HV9318	JMYSREA4AWZ000275
1095	HU9910	JMYSREA4AWZ000315
1096	KZ9259	JMYSREA4AWZ000393
1097	LR9323	JMYSREA4AWZ000453
1098	GM9209	JMYSREA4AWZ000462
1099	JT9203	JMYSREA4AXZ000127
1100	JA9485	JMYSREA4AXZ000140
1101	HG977	JMYSREA4AXZ000144
1102	HZ9402	JMYSREA4AXZ000164
1103	GA9893	JMYSREA4AXZ000196
1104	JW9934	JMYSREA7A1Z000150
1105	CU9996	JMYSREA4AVZ000129
1106	EP9990	JMYSREA4AVZ000352
1107	EY9188	JMYSREA4AVZ000606
1108	HD9208	JMYSREA4AVZ000786
1109	HD9026	EA4A0000114
1110	KW9855	JMYSREA4AVZ001016

	Reg Mark	Chassis Number
1111	EX9986	JMYSREA4AWZ000231
1112	KM9978	JMYSREA7A2Z000203
1113	GV9175	JMYSREA2AVZ002522
1114	HB9461	JMYSREA4AVZ000197
1115	JB951	JMYSREA4AVZ000232
1116	DM910	JMYSREA4AVZ000443
1117	JV9020	JMYSREA4AVZ000457
1118	HD9232	JMYSREA4AVZ000621
1119	EK991	JMYSREA4AVZ000915
1120	KZ9188	JMYSREA4AVZ000936
1121	KL9377	JMYSREA4AVZ001038
1122	JV9144	JMYSREA4AVZ001091
1123	HF9964	JMYSREA4AVZ001122
1124	GK9891	JMYSREA4AVZ001200
1125	ES932	JMYSREA4AVZ001338
1126	DV9313	JMYSREA4AVZ001406
1127	JE9252	JMYSREA4AVZ001516
1128	36940	JMYSREA4AVZ001521
1129	KH9949	JMYSREA4AVZ001708
1130	JE9406	JMYSREA4AWZ000161
1131	LL9831	JMYSREA4AWZ000212
1132	HB9370	JMYSREA4AWZ000241
1133	KF9845	JMYSREA4AWZ000283
1134	EC9578	JMYSREA4AWZ000445
1135	JE9637	JMYSREA4AXZ000151
1136	GB9298	JMYSREA4AXZ000476
1137	JT9203	JMYSREA7A1Z000127
1138	JW9682	JMYSREA7A1Z000140
1139	KE9203	JMYSREA7A2Z000105
1140	JJ936	JMYSREA7A2Z000206

車輛安全召回資訊

Vehicle Safety Recall Information

製造商 Make: Mitsubishi Motors Corporation

型號 Model: Galant EA2A, EA4A, EA7A

項目 Subject: 更換冷氣風機阻力

Replacement of Air Condition blower fan power transistor

受影響車輛的車輛識別號碼:

Involved Vehicle Identification Numbers:

	Reg Mark	Chassis Number
1141	GG1611	JMYSREA4AVZ000622
1142	GF287	JMYSREA4AVZ001454
1143	HG1213	JMYSREA4AWZ000261
1144	JW3889	JMYSREA4AXZ000416
1145	JL2220	JMYSREA4AVZ001501
1146	CM3233	JMYSREA4AVZ000595
1147	HP3929	JMYSREA4AVZ000537
1148	BX3183	JMYSREA4AVZ000174