

車輛安全召回資訊

Vehicle Safety Recall Information

10000310

製造商 Make: Mitsubishi Motors Corporation

型號 Model: L200 Sportero KB4T

項目 Subject: 檢查上搖臂托架螺栓扭矩

Fixing bolt tightening torque check at front upper arm ball joint portion

受影響車輛的車輛識別號碼:

Affected Vehicle Identification Numbers:

| | |
|----|-------------------|
| 1 | MMBJNKB407D168228 |
| 2 | MMBJNKB407D168358 |
| 3 | MMBJNKB407D168414 |
| 4 | MMBJNKB407D168540 |
| 5 | MMBJNKB407D168644 |
| 6 | MMBJNKB407D168754 |
| 7 | MMBJNKB407D168779 |
| 8 | MMBJNKB407D168796 |
| 9 | MMBJRKB407D168268 |
| 10 | MMBJRKB407D168437 |
| 11 | MMBJRKB407D168448 |
| 12 | MMBJRKB407D168453 |
| 13 | MMBJRKB407D168548 |
| 14 | MMBJRKB407D168922 |
| 15 | MMBJRKB407D169317 |
| 16 | MMBJRKB407D169323 |
| 17 | MMBJNKB407D170912 |
| 18 | MMBJNKB407D170968 |
| 19 | MMBJNKB407D171005 |
| 20 | MMBJNKB407D171076 |
| 21 | MMBJNKB407D171088 |
| 22 | MMBJNKB407D171137 |
| 23 | MMBJRKB407D170757 |
| 24 | MMBJRKB407D171071 |
| 25 | MMBJRKB407D171272 |
| 26 | MMBJRKB407D171357 |
| 27 | MMBJRKB407D171493 |
| 28 | MMBJRKB407D173421 |
| 29 | MMBJRKB407D173632 |
| 30 | MMBJRKB407D173759 |
| 31 | MMBJRKB407D173939 |
| 32 | MMBJRKB407D174113 |
| 33 | MMBJRKB407D174109 |

| | |
|----|-------------------|
| 34 | MMCJRKB409D006222 |
| 35 | MMCJRKB409D006448 |
| 36 | MMCJRKB409D006487 |
| 37 | MMCJRKB409D006509 |
| 38 | MMCJNKB409D006404 |
| 39 | MMCJNKB409D006570 |
| 40 | MMCJNKB409D006498 |
| 41 | MMCJRKB409D006602 |
| 42 | MMCJNKB409D006575 |
| 43 | MMCJNKB409D006626 |
| 44 | MMCJRKB409D006625 |
| 45 | MMCJNKB409D006670 |
| 46 | MMCJRKB409D006682 |
| 47 | MMCJNKB409D006508 |
| 48 | MMCJNKB409D006741 |
| 49 | MMCJRKB409D006715 |
| 50 | MMCJRKB409D006718 |
| 51 | MMCJRKB409D006731 |
| 52 | MMCJNKB409D006568 |
| 53 | MMCJNKB409D006643 |
| 54 | MMCJRKB409D006622 |
| 55 | MMCJRKB409D006624 |
| 56 | MMCJRKB409D006293 |
| 57 | MMCJNKB409D008435 |
| 58 | MMCJRKB409D008444 |
| 59 | MMCJRKB409D008460 |
| 60 | MMCJRKB409D008499 |
| 61 | MMCJNKB409D008554 |
| 62 | MMCJRKB409D008533 |
| 63 | MMCJRKB409D008552 |
| 64 | MMCJRKB409D008556 |
| 65 | MMCJNKB409D008456 |
| 66 | MMCJRKB409D008559 |