

## 安全召回詳情

編號	10000112
製造商	Ford Motor Escape
車輛類別	
型號	Ford Escape
代理商(電話)	森那美汽車服務有限公司 (Tel:2416 2111)
主題	Replacement fo Front Safety Belt Buckle Cover
進度	Completed
受影響車輛的底盤號碼	N/A
缺陷簡述及忽略的可能後果	As informed by Ford Motor Company, a plastic post inside the front seat safety belt buckle cover may break, allowing the buckle internal latch mechanism to wedge against the broken post. This may lead to a "no latch" condition in which the tongue does not the buckle, or a "partial latch" condition in which the tongue may be inserted into buckle and appear engaged when it is not.
修正行動	Will contract affected customers via direct phone call requesting them to return their vehicle to us for replacement of front safety belt buckle cover.
製造日期	Escape (2001) production
開始日期	01/03/2004
完成日期	11/06/2012