

安全召回詳情

Ref No	10000748
Manufacturer	UD truck
Vehicle Class	中/重型貨車
Model/Type	CWB5E,GKB5E,GKB5Y
Dealer (phone no)	躍達汽車有限公司(3713 1788)
Subject	更換動力輔助系統液壓喉管
Progress	進行中
Affected Vehicle Identification Number (VIN)	見以下表列:
Description of Defect, how it came to light, and possible consequences if ignored.	動力轉向泵軟管佈置不當可能會導致軟管損壞，導致動力轉向油洩漏，最終導致方向盤操作力增大。
Remedial Action	廠方要求有關之所有車輛需更換動力輔助系統液壓喉管。
Build Dates	2009-2011
Launch Date	20/12/2011
Tentative Date of Recall Completion	30/06/2018

1	CWB5E00001
2	CWB5E00002
3	CWB5E00012
4	CWB5E00013
5	CWB5E00014
6	CWB5E00015
7	CWB5E00016
8	CWB5E00017
9	CWB5E00018
10	CWB5E00039
11	CWB5E00040
12	CWB5E00041
13	CWB5E00066
14	CWB5E00067
15	CWB5E00073
16	CWB5E00074
17	CWB5E00075
18	CWB5E00078
19	CWB5E00080

20	CWB5E00082
21	CWB5E00083
22	CWB5E00087
23	CWB5E00088
24	CWB5E00090
25	CWB5E00091
26	CWB5E00094
27	CWB5E00098
28	CWB5E00099
29	CWB5E00093
30	CWB5E00100
31	CWB5E00101
32	CWB5E00112
33	CWB5E00113
34	CWB5E00114
35	CWB5E00117
36	CWB5E00118
37	CWB5E00120
38	GKB5E00003

39	GKB5E00011
40	GKB5E00012
41	GKB5E00019
42	GKB5E00020
43	GKB5E00021
44	GKB5E00022
45	GKB5E00047
46	GKB5E00048
47	GKB5E00049
48	GKB5E00050
49	GKB5E00051
50	GKB5E00052
51	GKB5E00053
52	GKB5E00054
53	GKB5E00055
54	GKB5E00068
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	

78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	

117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
150	
151	
152	
153	
154	
155	
156	

157	
158	
159	
160	
161	
162	
163	
164	
165	
166	
167	
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	
195	
196	

197	
198	
199	
200	
201	
202	
203	
204	
205	
206	
207	
208	
209	
210	
211	
212	
213	
214	
215	
216	
217	
218	
219	
220	
221	
222	
223	
224	
225	
226	
227	
228	
229	
230	
231	
232	
233	
234	
235	
236	

237	
238	
239	
240	
241	
242	
243	
244	
245	
246	
247	
248	
249	
250	
251	
252	
253	
254	
255	
256	
257	
258	
259	
260	
261	
262	
263	
264	
265	
266	
267	
268	
269	
270	
271	
272	
273	
274	
275	
276	

277	
278	
279	
280	
281	
282	
283	
284	
285	
286	
287	
288	
289	
290	
291	
292	
293	
294	
295	
296	
297	
298	
299	
300	
301	
302	
303	
304	
305	
306	
307	
308	
309	
310	
311	
312	
313	
314	
315	
316	

317	
318	
319	
320	
321	
322	
323	
324	
325	
326	
327	
328	
329	
330	
331	
332	
333	
334	
335	
336	
337	
338	
339	
340	
341	
342	
343	
344	
345	
346	
347	
348	
349	
350	
351	
352	
353	
354	
355	
356	

357	
358	
359	
360	
361	
362	
363	
364	
365	
366	
367	
368	
369	
370	
371	
372	
373	
374	
375	
376	
377	
378	
379	
380	
381	
382	
383	
384	
385	
386	
387	
388	
389	
390	
391	
392	
393	
394	
395	
396	

397	
398	
399	
400	
401	
402	
403	
404	
405	
406	
407	
408	
409	
410	
411	
412	
413	
414	
415	
416	
417	
418	
419	
420	
421	
422	
423	
424	
425	
426	
427	
428	
429	
430	
431	
432	
433	
434	
435	
436	

437	
438	
439	
440	
441	
442	
443	
444	
445	
446	
447	
448	
449	
450	
451	
452	
453	
454	
455	
456	
457	
458	
459	
460	
461	
462	
463	
464	
465	
466	
467	
468	
469	
470	
471	
472	
473	
474	
475	
476	

477	
478	
479	
480	
481	
482	
483	
484	
485	
486	
487	
488	
489	
490	
491	
492	
493	
494	
495	
496	
497	
498	
499	
500	
501	