

Transport Department Notice

Temporary Traffic Arrangements on Fanling Highway Northbound and Tai Wo Service Road West, Tai Po and North District

Notice is hereby given that to facilitate the road works on Fanling Highway and Tai Wo Service Road West, the following temporary traffic and transport arrangements will be implemented from 12.45 am to 5.30 am on 28 August 2016:

(I) ROAD CLOSURE

from 12.45 am to 5.30 am

The section of Fanling Highway northbound from Lam Kam Road Interchange to So Kwun Po Road roundabout will be closed to all vehicular traffic.

from 2.00 am to 5.30 am

The section of Tai Wo Service Road West from its junction with the slip road connecting with Tai Wo Service Road East to a point about 450 metres north of the same junction will be closed to all vehicular traffic.

(II) TRAFFIC DIVERSION

from 12.45 am to 2.00 am

Vehicles on Fanling Highway northbound heading for Fanling and Sheung Shui will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road westbound, slip road, Pak Wo Road eastbound, Jockey Club Road northbound, So Kwun Po Road westbound, So Kwun Po Road roundabout and Fanling Highway northbound.

from 2.00 am to 5.30 am

(a) Vehicles on Fanling Highway northbound heading for Fanling and Sheung Shui will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Kiu Tau Road westbound, Ming Yin Road westbound, Wah Ming Road roundabout, Wah Ming Road eastbound, Pak Wo Road eastbound, Jockey Club Road northbound, So Kwun Po Road westbound, So Kwun Po Road roundabout and Fanling Highway northbound.

- (b) Vehicles on Wah Ming Road roundabout heading for Tai Wo Service Road West southbound will be diverted via Ming Yin Road eastbound, Kiu Tau Road eastbound and Tai Wo Service Road West southbound.

(III) PUBLIC TRANSPORT SERVICES ARRANGEMENTS

from 12.45 am to 2.00 am

(A) Franchised Bus Services

- a) KMB route nos. 270A (Sheung Shui bound), 270S (Luen Wo Hui bound) and 278X (Sheung Shui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road westbound, Wah Ming Road roundabout, Wah Ming Road eastbound and Pak Wo Road northbound before resuming its normal routing.
- b) KMB route no. 277X (Luen Wo Hui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road westbound and Wah Ming Road roundabout before resuming its normal routing. The en-route stop at Wo Hing Tsuen will be temporarily suspended.
- c) LWB route no. N42A (Luen Wo Hui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road westbound, Wah Ming Road roundabout, Wah Ming Road eastbound, Pak Wo Road northbound, So Kwun Po Road eastbound and So Kwun Po Road roundabout before resuming its normal routing.

(B) Green Minibus Services

- a) GMB Route no. 501S (Sheung Shui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road westbound and Wah Ming Road roundabout before resuming its normal routing.
- b) GMB Route no. 616S (Lok Ma Chau bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Wo Hing Road westbound, slip road, Pak Wo Road eastbound, Jockey Club Road northbound, So Kwun Po Road westbound, So Kwun Po Road roundabout and Fanling Highway northbound before resuming its normal routing.

from 2.00 am to 5.30 am

(A) Franchised Bus Services

- a) KMB route no. 270S (Luen Wo Hui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Kiu Tau Road westbound, Ming Yin Road westbound, Wah Ming Road roundabout, Wah Ming Road eastbound and Pak Wo Road northbound before resuming its normal routing.
- b) KMB route no. N73 (Lok Ma Chau bound) will be diverted via Kiu Tau Road westbound, Ming Yin Road westbound and Wah Ming Road roundabout before resuming its normal routing. The en-route stops at Kau Lung Hang, Ho Ka Yuen, Wo Hop Shek San Tsuen and Wo Hing Tsuen will be temporarily suspended.
- c) KMB route no. N73 (Sha Tin bound) will be diverted via Wah Ming Road roundabout, Ming Yin Road eastbound and Kiu Tau Road eastbound before resuming its normal routing. The en-route stops at Wo Hing Tsuen, Wo Hing Road Fanling, Ho Ka Yuen and Kau Lung Hang will be temporarily suspended.

(B) Green Minibus Services

- a) GMB Route no. 501S (Sheung Shui bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Kiu Tau Road westbound, Ming Yin Road westbound and Wah Ming Road roundabout before resuming its normal routing.
- b) GMB Route no. 616S (Lok Ma Chau bound) will be diverted via Lam Kam Road Interchange, Tai Wo Service Road West northbound, Kiu Tau Road westbound, Ming Yin Road westbound, Wah Ming Road roundabout, Wah Ming Road eastbound, Pak Wo Road northbound, So Kwun Po Road eastbound, So Kwun Po Road roundabout and Fanling Highway northbound before resuming its normal routing.
- c) GMB Route no. 58S (Sheung Shui bound) will be diverted via Kiu Tau Road westbound, Ming Yin Road westbound, Wah Ming Road roundabout, Wo Hing Road eastbound and slip road before resuming its normal routing.

- d) GMB Route no. 58S (Mongkok bound) will be diverted via Wo Hing Road westbound, Wah Ming Road roundabout, Ming Yin Road eastbound and Kiu Tau Road eastbound before resuming its normal routing.

Appropriate traffic aids will be erected on site. Motorists are advised to follow the instructions on site and drive in utmost care.

LAW Fung-ping, Cinderella *Commissioner for Transport (Acting)*